

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

HOBBS OCD

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

AUG 22 2012

RECEIVED

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>WELL API NO. 30-025-27275</p>
<p>1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/></p>		<p>5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/></p>
<p>2. Name of Operator ConocoPhillips Company</p>		<p>6. State Oil & Gas Lease No. E-7585</p>
<p>3. Address of Operator P. O. Box 51810 Midland, TX 79710</p>		<p>7. Lease Name or Unit Agreement Name EAST VACUUM GSA UNIT TRACT# 2980</p>
<p>4. Well Location Unit Letter <u>F</u> : 1980 feet from the <u>NORTH</u> line and 1980 feet from the <u>WEST</u> line Section <u>29</u> Township <u>17S</u> Range <u>35E</u> NMPM County <u>LEA</u></p>		<p>8. Well Number 004</p>
<p>11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3970' RKB</p>		<p>9. OGRID Number 217817</p>
		<p>10. Pool name or Wildcat VACUUM; GRAYBURG/SAN ANDRES</p>

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☒

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Remove HH. POOH w/ rods & pump. ND WH NU BOP. TOO H w/ tbg. RIH w/ RBB set @ 4500' & pkr set @ 4468'. PT- est leak @ 5" below surf on 5 1/2" csg. Put clamp on 5 1/2" csg. PT- 550# held. TOO H w/ pkr & RBP. RIH w/ RBP set @ 2525'. ND BOP. Made csg repairs by cutting off tbg & welded another piece on. PT 500#/ 15 min- held. Install WH. NU BOP. TOO H w/ RBP. TIH w/ 141 jts, 2 7/8", 6.4#, J-55 tbg reset @ 4657'. ND BOP NU WH. TIH w/ rods & pump spaced out. Hung HH. RDMO

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ashley Martin TITLE Staff Regulatory Technician DATE 08/14/2012

Type or print name Ashley Martin E-mail address: Ashley.Martin@conocophillips.com PHONE: (432)688-6938

For State Use Only

APPROVED BY: [Signature] TITLE Dist. Mgr DATE 8-23-2012

Conditions of Approval (if any):