

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

AUG 27 2012

WELL API NO. 30-005-29179
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB-1521
7. Lease Name or Unit Agreement Name SOUTH TOBAC STATE UNIT
8. Well Number 1Y
9. OGRID Number 155615
10. Pool name or Wildcat CHAVAROO; SAN ANDRES
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4392 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐
2. Name of Operator
NADEL AND GUSSMAN PERMIAN, L.L.C.
3. Address of Operator
601 N. MARIENFELD SUITE 508 MIDLAND TEXAS 79701

4. Well Location
Unit Letter N : 850 feet from the NORTH line and 830 feet from the WEST line.
Section 29 Township 8S Range 33E NMPM County CHAVES

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

CIBP AND 35' OF CEMENT AT 4,220' SET ON 10/10/2011

PXA PROCEDURE:

- 1) TAG CIBP AND CEMENT AT 4,220FT. CIRCULATE MUD.
- 2) SET 25 SACK PLUG AT 2,580'
- 3) SET 25 SACK PLUG AT 1,900' WOC AND TAG.
- 4) PERF AT 450, SQUEEZE 135 SACKS AND LEAVE CASING FULL TO SURFACE.
- 5) CLEAN LOCATION OF ALL EQUIPMENT, COVER CELLAR, REMOVE WELLHEAD SET PA MARKER.

Spud Date:

5/10/11

Rig Release Date:

5/18/11

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE ENGINEER

DATE 8/23/2012

Type or print name JASON GOSS E-mail address: JGOSS@NAGUSS.COM PHONE: 432-682-4429

For State Use Only

APPROVED BY:

TITLE

DATE

Conditions of Approval (if any):

AUG 27 2012

Nadel & Gussman Permian, LLC

LEASE: South Tobac St. Unit
 FIELD: Chavaroo, San Andres
 LOCATION: 850' FNL 830' FWL
 SPUD DATE: 5/11/2011
 CONTRACTOR: Patriot Rig #1

WELL NO: 1Y
 COUNTY: Chaves
 LEGAL: Sec. 29 T8S R33E
 DRAWN BY: Jason Goss
 DATE: 8/23/2012

API #: 30-005-29179
 STATE: New Mexico
 GL: 4394
 DF: 4412.5
 KB: 18.5

South Tobac St. Unit Well No. 1Y

