

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161

1625 N. French Dr., Hobbs, NM 88240

District II - (575) 748-1283

811 S. First St., Artesia, NM 88201

District III - (505) 334-6008

1000 Rio Brazos Rd., Aztec, NM 87419

District IV - (505) 476-3460

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised August 1, 2011

WELL API NO. 30-025-35485	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. B-2656	
7. Lease Name or Unit Agreement Name Hardy 36 State	
8. Well Number 31	
9. OGRID Number 217817	
10. Pool name or Wildcat North Hardy Tubbs-Drinkard	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3500' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: Recomplete <input checked="" type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Report change of sand frac to acid frac.

7/23/12 NDWH & NUBOP. RIH w/ RBP & set @ 6951'

7/24/12 RU WL to perf. Perf 2spf @ Drinkard F/6834'-6851', 6824'-6831', 6812'-6822', 6804'-6810', 6780'-6795'. RD WL

7/25/12 RIH w/pkr & set @ 6595'. Acid w/15% HCL, dropping balls. Release pkr & Pull RBP up hole to 6650' & re-set & pkr to 6630', test RBP to 1000# - held. POH w/pkr.

7/30/12 RU WL Perf Tubbs F/6608'-6599', 6548'-6522', 6514'-6492', 6474'-6458'.

7/31/12 Pump 2000 gal acid, dropping balls. 8/2/12 Set pkr @ 6344'.

8/3/12 Pumped 4000 gals gelled water, 10,000 gal 15% NEFE acid.

8/7/12 Release pkr circ fill off RBP. Release RBP POOH w/pkr & RBP. RIH w/222 jts, 2 7/8", 6.5#, J-55 tbg & set @ 7002'.

NDBOP & set TAC NUWH

8/8/12 Install Rods & pump, space well out. RDMO

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Staff Regulatory Technician

DATE 08/20/2012

Type or print name Rhonda Rogers

E-mail address: rogersr@conocophillips.com

PHONE: (432)688-9174

For State Use Only

APPROVED BY:

TITLE

Petroleum Engineer

DATE

AUG 30 2012

Conditions of Approval (if any):

PA Hardy Strawn, North