		INTERIOR	HOBBER	CD	( C	ORM APPROVED DMB No. 1004-0137 pires: October 31, 2014	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-ertific and 4 2012 abandoned well. Use Form 3160-3 (APD) for such proposals.						6. If Indian, Allottee or Tribe Name	
SUBMI	T IN TRIPLICATE - Other	r instructions on pag	ye 2 RECE	VED	7. If Unit of CA/Agree	ment, Name and/or No.	
					1		
Oil Well Gas Well Other						L #2H	
2. Name of Operator OCCIDENTAL PERMIAN LTD					9. API Well No. 30-045-40280		
3a. Address PO BOX 4294; HOUSTON, TX 77210 3b. Pho			. Phone No. (include area code)		10. Field and Pool or E	xploratory Area	
					LUSK BONE SPRIN	G, SOUTH (41430)	
4. Location of Well (Footage, Sec., T., R., M, or Survey Description) 141' FNL & 2347' FWL, NENW (C) SEC 33, T19S R32E						itate	
12. CHEC	CK THE APPROPRIATE BO	OX(ES) TO INDICAT	TE NATURE OF	FNOTI	CE, REPORT OR OTHE	ER DATA	
MISSION	TYPE OF ACTION						
	Acidize	Deepen	· [	Prod	uction (Start/Resume)	Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Tr	reat [	Recl	amation	Well Integrity	
Subsequent Report	Casing Repair	New Const	truction	Reco	omplete	Other Changes to 5.5"	
Cubsequent report		Plug and A	bandon [	Tem	porarily Abandon	Cement Job	
ent Notice	Convert to Injection	🔲 Plug Back	Γ	] Wate	er Disposal		
	BUR SUNDRY N oned well. SUBMI Gas V MIAN LTD TX 77210 ootage. Sec., T., W (C) SEC 33, TH 12. CHEC MISSION	DEPARTMENT OF THE BUREAU OF LAND MAN SUNDRY NOTICES AND REPO to use this form for proposals oned well. Use Form 3160-3 (A SUBMIT IN TRIPLICATE – Othe Gas Well Other MAN LTD TX 77210 Octage. Sec., T.,R.,M, or Survey Description W (C) SEC 33, T19S R32E 12. CHECK THE APPROPRIATE BO MISSION	DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELL of use this form for proposals to drill or to re- bined well. Use Form 3160-3 (APD) for such p SUBMIT IN TRIPLICATE – Other instructions on page I Gas Well Other MAN LTD TX 77210 3b. Phone No. (incl 713-513-6640 ootage. Sec., T.,R.,M, or Survey Description) W (C) SEC 33, T19S R32E 12. CHECK THE APPROPRIATE BOX(ES) TO INDICAT MISSION Acidize Deepen Alter Casing Fracture Ti Casing Repair New Const Change Plans Plug and A	DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT   SUNDRY NOTICES AND REPORTS ON WELLS of use this form for proposals to drill or to re-enternal oned well. Use Form 3160-3 (APD) for such proposals.   SUBMIT IN TRIPLICATE – Other instructions on page 2   SUBMIT IN TRIPLICATE – Other instructions on page 2   I Gas Well   I Other   MAN LTD 3b. Phone No. (include area code) 713-513-6640   TX 77210 3b. Phone No. (include area code) 713-513-6640   TX 77210 Internal Structure Proposals   I Acidize   I Deepen   I Acidize   I Acidize   I Deepen   I Acidize   I New Construction   I Casing Repair   I New Construction	DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Image: Construction of the second se	DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Ex   SUNDRY NOTICES AND REPORTS ON WELLS on use this form for proposals to drill or to re-erft and 4 2012 5. Lease Serial No. NMNM01135   SUBMIT IN TRIPLICATE – Other instructions on page 2 FECENED   SUBMIT IN TRIPLICATE – Other instructions on page 2 7. If Unit of CA/Agree   MAN LTD 8. Well Other   MAN LTD 9. API Well No. 713-513-6640   Not close Sec., T.R.M, or Survey Description) 11. County or Parish, S LEA COUNTY, NM   12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHE MISSION Production (Start/Resume) Production (Start/Resume)   Acidize Deepen Production (Start/Resume)   Acidize Deepen Production (Start/Resume)   Alter Casing Practure Treat Recelamation   Casing Repair New Construction Recomplete   The Casing Repair Plug and Abandon Temporarily Abandon	

.

I

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Please see the attached description of the changes to the cement job that was verbally approved by engineer on-call, Chris Walls. If there are any questions or concerns, please feel free to contact us at any time.

14. I hereby certify that the	e foregoing is true and corre	ct Name (Printed/1yped)				
Jennifer Duarte (jennifer_duarte@yahoo.com)			e Regulatory Analyst			
Signature	1 ~	· - 1 D	ate 08/27/2012			
<i>—</i> ,	T	HIS SPACE FOR FEDER	AL OR STATE OFFICE USE	IACULY IEU I VII III		
Approved by				Ctoo		
	·		itle	Jate AIIG 3 0 2012		
Conditions of approval, if ar that the applicant ho entitle the applicar	ny, are attached. Approval or equelle the percent	of this notice does not warrant or certains in the subject lease which would		1 /SI CIL S MANAGEMENT		
Litle 18 U.S.C. Section 1( fictitious or fraudulent states		on 1212, make it a crime tor any personant to any matter within its jurisdiction.	n knowingly and willfully to make to any depa			
(Instructions on page 2)						

SEP U 5 201

The original plan was to perform a 3 stage cement job using a DV tool (~8044') and POST tool (~4288') to help ensure we have good cement throughout the well bore.

- The 1<sup>st</sup> cement stage went fine. We pumped a total of 430 bbls of cement and circulated 150 bbls of cement back to surface
- We then waited on cement a total of 8 5 hours (waited on Halliburton for an additional 2.5 hours after the planned 6 hours WOC)
- Once Halliburton arrived with the remainder of the 2<sup>nd</sup> stage cement blend we proceeded to pump 362 bbls of lead cement and 24 bbls of tail cement (386 bbls total) with full returns throughout the job.
- We then dropped the DV tool closing plug and displaced, pumping 7 bbls over calculated displacement volume and were still unable to close the DV tool. We had some died spacer to surface but still had not seen any cement.
- Decision was to keep circulating mud and either bump the plug and close the DV tool or circulate out all the cement.
- The plug never bumped, so we circulated out all of the cement (~380 bbls seen at surface).
- The BLM on-call Engineer was informed (Chris Walls) of the situation and has given us approval to re-pump the 2<sup>nd</sup> stage and bring cement <u>to surface</u>, then shut in and WOC (at least 6 hours) if the plug does not bump &/or DV tool does not close. We will then WOC for at least 4 hours. An additional 150-200 sacks of lead cement will be pumped from the original volumes to ensure we get cement to surface.
- While waiting on more cement to arrive on location, the rig ran a sinker bar down on wireline and confirmed we are clear to the top of the DV tool. We tagged up right around 8044' which is where the DV tool is. The plug could be stuck/wedged on top of the DV tool, in the DV tool but not closing it for some reason or was pumped through the DV tool?
- Weatherford has confirmed a regular wiper plug will not pass through the POST tool, so we will have to drop the same plug we dropped the first time.
- Weatherford has the cancellation plug we can drop after we WOC, which will shift the POST tool to the closed position.