
Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Submit 1 Copy To Appropriate District Office District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM District II – (575) 748-1283 811 S. First St. Artesia, NM 88210	ergy, Minerals and Natural Resources	Revised August 1, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM. 832433 District II – (575) 748-1283	T. GOMGEDAN EVON DAMAGON	30-025-09865
711 S. 1 115 SE, 7 11 COM, 1 117 CODITO	IL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 100 Blazos rai, 112100, 1111 0 12-0	Santa Fe, NM 87505	STATE FEE X
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa FC, INVI 67303	6. State Oil & Gas Lease No.
87505 CLINDRY NOTICES AN	D REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE "APPLICATION F	DRILL OR TO DEEPEN OR PLUG BACK TO A	Priest
PROPOSALS.) 1. Type of Well: Oil Well X Gas We	ll Other	8. Well Number 4
2. Name of Operator Celero Energy II, LP		9. OGRID Number 247128
3. Address of Operator 400 W. Illinois, Ste	1601	10. Pool name or Wildcat
Midland, TX 7970	1001	Denton (Wolfcamp)
4. Well Location		
Unit Letter D : 660	feet from the N line and 990	feet from the W line
Section 1	Township 15S Range 37E	NMPM County Lea
li de la	evation (Show whether DR, RKB, RT, GR, etc.,	
English Turk Control of the Control		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
	AND ABANDON 🖾 REMEDIAL WOR	
k.	GE PLANS 🛛 COMMENCE DR	_
	IPLE COMPL	T JOB 🔲
DOWNHOLE COMMINGLE		
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
Change approved to TA to P&A.		
 Circ salt mud to 400'. PU, spot 35 sx @ 1900'. WOC & tag at/above 1800'. POOH. RIH w/ pkr, set & test. Perf 4 @ 407'. Sqz 70 sx & displace no deeper than 300'. POOH w/ pkr. RIH w/ BP & perf sub & tag 		
TOC at/above 307' after a min of 4 hrs WOC. Circ salt mud to surf.		
3. POOH LD. Spot 10 sx @ 30 to surf.		
4. RDMO. Cut off WH & set P&A marker. Clean & relcaim location.		
25 100		
7 5 00	,	
		——————————————————————————————————————
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
4 · d/	, —	
SIGNATURE) WA HEV.	TITLE Regulatory Analyst	DATE <u>09/06/2012</u>
Type or print name Lisa Hunt	E-mail address: <u>lhunt@celeroene</u>	rgy.com PHONE: (432)686-1883
For State Use Only		
APPROVED BY: Mach White Loupling Officer DATE 09-06-2012		
Conditions of Approval (if any):	i i i i i i i i i i i i i i i i i i i	DATE - 1 - 22

Priest #4 - 660' FNL & 990' FWL of Sec. 1, T-15S, R-37E, Unit Letter "D"



PBTD @ 9443' TD @ 9450'