

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised August 1, 2011

WELL API NO.	30-025-02979
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1838-1
7. Lease Name or Unit Agreement Name	East Vacuum GB-SA Unit Tract 3236
8. Well Number	004
9. OGRID Number	217817
10. Pool name or Wildcat	Vacuum; Grayburg-San Andres
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	3974' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>
2. Name of Operator ConocoPhillips Company
3. Address of Operator P. O. Box 51810 Midland, TX 79710
4. Well Location Unit Letter F : 1980' feet from the North line and 1980' feet from the West line Section 32 Township 17S Range 35E NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3974' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: Record clean-up, LOV ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Prior to RU on well, need to notify NMOCD. RU WSU, and TOO H with rods and pump. Visually inspect the rods and boxes for pitting and wear, change out as needed. Send pump to Don-Nan to be R&R, will not run same pump back, see description under pump. Save a sample of any foreign material in pump and notify Production Specialist of the sample. NDWH, NUBOP, review JSA for change in job scope. COOH scanning tubing and lying down. MO production tubing and MI and tally work string. TIH with bit, scrapper, and tubing and TFF, if fill is present, clean out to TPBD. COOH with tubing, scrapper, and bit. TIH with RBP, packer and tubing and set RBP @ +/- 3800', pull up 1jt and set packer, RU pump truck to tubing and pressure test RBP/ packer to 500 psi. If tubing holds, RU pump truck to casing and test casing/packer to 500 psi. If casing/packer test fails, come up hole and isolate leak. After repairs, TIH with tubing, retrieving head and retrieve RBP, COOH with tubing, retrieving head and RBP. TIH with packer and tubing an set packer +/- 4300'. Pump 2500 gals of Xylene and 2500 gals of 15% HCL mixed together with additives. Flush tubing with 35bbls fresh water. TOO H laying down work string and packer. MO work string. MI production tubing. TIH as to Rod and Tubing Configuration. NDBOP, NUWH, TIH with pump and rods, land pump, load and test, space .

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Staff Regulatory Technician

DATE 09/04/2012

Type or print name Rhonda Rogers

E-mail address: rogersr@conocophillips.com

PHONE: (432)688-9174

For State Use Only

APPROVED BY:

TITLE

DATE

9-13-2012

Conditions of Approval (if any):

SEP 13 2012