Submit 1 Copy To Appropriate District Office	State of New Mexico			/ Form C-103
District 1 - (575) 393-6161	Energy, Minerals and Natural Resources			Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	ench Dr., Hobbs, NM 88240		WELL API NO. 30-025-24332 ✓	
1 S. First St., Artesia, National Strict III – (575) 334-6178 OIL CONSERVATION DIVISION 1220 South St. Francis Dr		5. Indicate Type of Lease		
		STATE FEE		
1000 Rio Brazos Rd., Aztec, NM 874102012 <u>District IV</u> – (505) 476-34607 P 17802012 Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Sama Fe, NM 87505				:
SUNDRYCK VIDES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			VACUUM G/B SAN ANDRES UNIT	
PROPOSALS.)			8. Well Nur	mber 4
1. Type of Well: Oil Well Gas Well Other INJECTOR			9. OGRID Number 4323	
2. Name of Operator CHEVRON U.S.A. INC.			7	
3. Address of Operator 15 SMITH ROAD, MIDLAND, TEXAS 79705			10. Pool name or Wildcat VACUUM G/B SAN ANDRES	
4. Well Location				/
Unit Letter M: 220 feet from the SOUTH line and 100 feet from the WEST line				
Section 1 Township 18-S Range 34-E NMPM County LEA				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
。				
12. Charle Ameromiata Day to Indianta Natura of Nation Papart or Other Data				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			≺ ·	☐ ALTERING CASING ☐
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A				_
DOWNHOLE COMMINGLE				
OTHER:		OTHER: MIT F	REPAIR	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
8-24-12: MIRU. 8-29: TIH W/SPEAR& TAG @ 4395. PUSH PKR TO 4402. TAG FISH @ 4401. MOVE PKR 5'. HUNG UP.				
JAR ON PKR. CAME LOOSE. HUNG UP @ 4060. JAR LOOSE. 8-30: JAR. 8-31: MILL OVER PKR @ 4025. MADE				
10 INCHES. 9-04: TIH W/SPEAR & LATCH ONTO PKR. PULL OUT. 9-06: TAG FILL @ 4402. C/O TO PBTD @				
4788. CIRC CLEAN. PULL & LAID DN 13 JTS TO PUT US ABOVE PERFS @ 4377. 9-07: SET RBP @ 4397. REL. SET				
PKR @ 4359. REL PKR & RBP. 9-10: NOTIFIED NMOCD OF MIT TEST. SET PKR @ 4395. PRETEST CSG.				
9-11-12: RAN CHART FOR NMOCD. (COPY OF CHART ATTACHED). PRESS CSG TO 550 PSI FOR 30 MINUTES.				
RIG DOWN. TURN OVER TO PRODUCTION.				
Court Date:	2: 21			
Spud Date:	Rig Release Da	ite:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
A)				
LM 11 160 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2				
SIGNATURE THE REGULATORY SPECIALIST DATE: 09-18-2012				
Type or print name: DENISE PINKERTON E-mail address: leakejd@chevron.com PHONE: 432-687-7375				
APPROVED BY: Wash Whitaken TITLE Compliance Officer DATE 09-19-2012				
Conditions of Approval (if any):				

