Form 3160-5 (August 2007)

(Instructions on page 2)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No NM 04591

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

	Use Form 3160-3 (A					
SUBMIT IN TRIPLICATE – Other instructions on page 2				7. If Unit of CA/Agreement, Name and/or No.		
I. Type of Well ✓ Oil Well Gas W	_		0 2 2012	8. Well Name and No. NEW MEXICO FED		
Name of Operator Devon Energy Production Company	, L.P.			9. API Well No. 30-025-29605	7	
3a. Address 333 W Sheridan Avenue, Oklahoma City, OK 7	3102-5010	3b. Phone No (includ 405-235-3611	EH	10. Field and Pool or E DELAWARE (CHER		1651
4. Location of Well (Footage, Sec., T., 2080 FNL & 600 FEL SEC 24 T18S R				11. Country or Parish, Lea County, NM	State	
12. CHEC	CK THE APPROPRIATE BO	X(ES) TO INDICATE NA	TURE OF NOTIO	CE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION			TYPE OF ACT	ION		
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Recl	uction (Start/Resume)	Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair Change Plans	New Constructio	n Tem	mplete porarily Abandon	Other Add Pay	
Final Abandonment Notice	Convert to Injection	Plug Back	Wate	Water Disposal		
following completion of the involve testing has been completed. Final determined that the site is ready for 10/3/11 - MIRU PU. POOH w/ rods 10/4/11 - RIH w/bit & scaper on tbg 10/5/11 - 10/6/11- TIH w/ pkr, set (to 7,180psi, load tbg w/25 bbls linea w/29,646# 20/40 BS. Tail w/ 23,93: 10/10/11 - 10/12/11 - Release pkr & 5,378', set pkr to test RBP to 2,000g 10/13/11 - 10/15/11 - RU BHI, fract lbs 20/40 WS & flush w/31 bbls line Set SN @ 5,531', TAC @ 5,300' & I	Abandonment Notices must be final inspection.) & pump, ND WH and NU to 5,900'; POOH. RU WL @ 5,790'. Tested csg to 2,0 ar gel, broke down perfs @ 2 # 16/30 Siber Prop & flus POOH w/tbg. RU WL, Ripsi, ok. Release pkr, pull ustreated perfs 5,331 - 5,366 ar gel. RD BHI, open well EOT @ 5,586'. POOH, NE	be filed only after all requirements of the BOP; release TAC & PC & RIH, perforate as follows, as a perforate as follows on the BOP; release TAC & PC & RIH, perforate as follows on the BOP; and the BOP; release to the BOP; rel	rements, including DOH w/tbg. ows: 5,674'-5,79 o down tbg, relea perfs 5,674-5,79 or control of the control of	reclamation, have been 0' w/ 60 holes. RD W se pkr, pull up hole & 90' w/ 3,000 gal 15% w/ 33 holes. RD WL. 0 psi. Prep to frac. ar gel,598 bbls Spectro DH w/tbg & pkr. CHC	or completed and the operator VL. Set @ 5,580'. RU BHI, to Acid, 792 bbls Spectra Fr TIH w/ RBP & pkr, set RE ra Frac 2500 X-Ling Gel v C, TIH w/ sand screen & S	est lines ac 2500 BP @ v/17,017 SN on tbg
14 I hereby certify that the foregoing is t Name (Printed/Typed) DAVID H. COOK	rue and correct	Title RE	Title REGULATORY SPECIALIST			
Signature 0 .	\mathcal{Q}_{-}	Date 09	/10/2012	ACCEPTED	FOR RECORD)
	THIS SPACE	FOR FEDERAL O	R STATE OF	FICE USE		
Approved by		Title		SEP	3 0 2012 Bate	
Conditions of approval, if any, are attache that the applicant holds legal or equitable entitle the applicant to conduct operations	title to those rights in the subject thereon	not warrant or certify of lease which would Off	ice K	BURFAU OF I	AND MANAGEMENT	
Title 18 U S.C. Section 1001 and Title 43 fictitious or fraudulent statements or repri			ingly and willfully			tes any fal