Submit 3 Copies To Appropriate District State of New Me Office Energy, Minerals and Natu	Form C-103 June 19, 2008				
District		ELL API NO.			
1625 N French Dr , Hobbs, NM 87240 OCD District II	N DIVISION	30-025-29905			
1 SUL W. Grand Ave. Artesia NW 88/10		Indicate Type of Lease			
District III 1000 Rio Brazos Rd, Aztec, Niger 109 2012 District IV 1220 South St. Fra Santa Fe, NM 8		STATE FEE 🗷 🥌			
1220 S St Francis Dr., Santa Fe, NM 87505	6.	6. State Oil & Gas Lease No.			
SUNDRY NOTICES AND REPORTS ON WE	LLS 7.	Lease Name or Unit Agreement Name:			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-10 PROPOSALS.)	OR PLUG BACK TO A 🛌	Eunice Monument South Unit 🦯			
1. Type of Well: Oil Well Gas Well Other Injection	/	8. Well Number 237			
2. Name of Operator	9.	OGRID Number			
3. Address of Operator	10	005380 . Pool name or Wildcat			
200 N. Loraine, Ste. 800 Midland, TX 79701		mice Monument; Grayburg-San Andres			
4. Well Location					
Unit Letter : 2194' feet from the Son	ith line and 64	0' feet from theVest line			
Section 3 Township 215		IMPM County Lea			
11. Elevation (Show whether	DR, KKB, KI, GR, etc.)				
12. Check Appropriate Box to Indicate	Nature of Notice, Rep	port, or Other Data			
NOTICE OF INTENTION TO:	SUBSE	SEQUENT REPORT OF:			
PERFORM REMEDIAL WORK 🗍 PLUG AND ABANDON 🗌	REMEDIAL WORK				
	COMMENCE DRILLING	OPNS.			
	CASING/CEMENT JOB				
	CASING/CEMENT JOB				
		9 .			
OTHER: RWTI	OTHER:				
13. Describe proposed or completed operations. (Clearly state all performing any proposed work). SEE RULE 1103. For Multiple or recompletion.					
XTO Energy, Inc would like to propose the following	proposal to return E	unice Monument South Unit #237 to			
injection: 1. DO CIBP @ 3677' CO to 3927'.	Der Under	mound Infordion Control Barry BE			
2. Set packer @ 3670', circ TCA w/pkr fluid.		round Injection Control Program Manual			
3. Perform MIT to 500 psi for 30 mins.	11.6 C Pa	acker shall be set within or less than 100			
4. Acidize w/1000 gals 20% 90/10 NEFE acid.	feet of the	e uppermost injection perfs or open hole.			
5. RWTI					
······································					
Spud Date: 05/05/1987 Rig Relea	ase Date:				
	·····				
I hereby certify that the information above is true and complete to the	e best of my knowledge an	d belief.			
,000 0 0	LERegulatory 2				
	stephanie_rabadue@xto nail address:	energy.comPHONE432-620-6714			
For State Use Only					
	rle Dist. M	DATE 10-10-201			
	CONDITION OF A	APPROVAL: Notify OCD Hobbs			
Conditions of Approval: The Operator shall give the OCD District office 24 hours notice before work begins		ior to running MIT Test & Chart.			

WELL NAME: EMSU 237 LOCATION: 2194' FSL & 640' FWL, SEC 3 T21S R36E FORMATION: GRBG SPUD DATE: 05/05/87 IP: COUNTY/STATE: LEA, NM LEASE: EUNICE MONUMENT CURRENT STATS: TA'D COMPL DATE: 05/24/87 API No: 30-025-29905







EMSU #237 WIW Reactivation Procedure Lea County, New Mexico September 26, 2012 AFE #: 1207394

ELEV	ATION:	GL – 3564' KB – 3581'	TD – 3954' PBTD – 3677'	
WELI	L DATA: Current Status:	TA'd.		
	Surface Casing:	8-5/8" 24ppf csg set at 1295' cemented with 900 sx. Cement circ to surface.		
	Prod. Casing:	5-1/2" 15.5 & 17ppf csg set at 3954' cemented with 700 sx. Cement circ to surface.		
	CIBP:	3677'		

COMPLETION:

Тор	Bottom	Length	Туре	Formation	SPF	Shots	Date	Comments
3677	3681	4	Plug	-	-	-	2002	CIBP
3744	3756	12	Perf	Grayburg	3	36	1997	Isolated
3766	3776	10	Perf	Grayburg	3	30	1997	Isolated
3786	3794	8	Perf	Grayburg	3	24	1997	Isolated
3800	3808	8	Perf	Grayburg	3	24	1997	Isolated
3814	3830	16	Perf	Grayburg	3	48	1997	Isolated
3838	3870	32	Perf	Grayburg	1	32	1987	Isolated

7

.

 \mathbb{C}^{n}

OBJECTIVE:

Reactivate and RWTI.

.



EMSU #237 WIW Reactivation Procedure Lea County, New Mexico September 26, 2012 AFE #: 1207394

RECOMMENDED PROCEDURE

(Verify that anchors have been set and tested per NMOCD and OSHA guidelines) **This is a Private well.**

- 1. MIRU PU. ND WH. NU BOP. RU reverse unit. PU and RIH with 4-3/4" bit, DC's and 4000' 2-7/8" 6.5 ppf J-55 WS. DO CIBP at 3677'. CO to 3927'.
- 2. POOH with WS, DC's and bit.
- 3. RIH with 5-1/2" injection packer, on/off tool and 2-3/8" 4.7 ppf J-55 IPC tubing. Set packer at 3670'. Circulate TCA with packer fluid.
- 4. Notify NMOCD 48 hrs. prior to performing MIT. Perform MIT to 500 psig for 30 min.
- 5. ND BOP. NU WH. RDMO PU.
- 6. RU acid company. Pump 1000 gals 20% 90/10 NEFE acid. RD acid company.
- 7. Open injection line. RWTI.

Prepared by:

Approved by:

Evelyn Serrano

Date

Kirk Houston

Date

James Fort

Date