

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161  
1625 N French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

HOBBS OGD

OIL CONSERVATION DIVISION

OC 1 - § 2012 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

Form C-103

Revised August 1, 2011

WELL API NO. 30-025-20168
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. A01375
7. Lease Name or Unit Agreement Name Wallace State
8. Well Number #6
9. OGRID Number 14462
10. Pool name or Wildcat Blinebry
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,538

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Me-Tex Oil & Gas, Inc.	
3. Address of Operator P.O. Box 2070, 119 E. Bender, Hobbs, NM 88240	
4. Well Location Unit Letter <u>K</u> : <u>4290</u> feet from the <u>S</u> line and <u>2310</u> feet from the <u>W</u> line Section <u>3</u> Township <u>21S</u> Range <u>36E</u> NMPM County <u>Lea</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,538	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Propose to kill well, pull 2 3/8" tubing, rods and pump. Go back in with RBP and set at 5870'. Would like to perforate at 5861', 5859', 5854', 5849', 5847', 5836', 5825', 5819', 5814', 5810' and 5806' with 2 JSPF. Set treating packer at 5770' and pump 2% KCL down the backside. Acidize with 7,000 gallons of 15% NFE acid and RNC ball sealers. Swab and return to production.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE LeAnn Whitehead TITLE Production Manager DATE October 17, 2012

Type or print name LeAnn Whitehead E-mail address: lwhitehead@metexoil.com PHONE: (575) 397-7750

For State Use Only

APPROVED BY: [Signature] TITLE Dist Mgr DATE 10-19-2012  
Conditions of Approval (if any):