	PIQW	Mexico Sin Con	servation	L'IVISIUN I Iriva		
2160 5 - 2012	UNITED STATE	1625 N	I. FTEHCH L	211VC		
	E INTERIOR			Expires: March 31, 2007		
	NAGEMENT	S	5. Lease Sen NMNM			
DECOMPANY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indiar	, Allottee or Tribe Name	
abandoned w	ell. Use Form 3160-3	(APD) for such prop	osals.	N/A	-	
SUBMIT IN TR	IPLICATE- Other inst	tructions on revers	e side.	7. If Unit or CA/Agreement, Name and/or No		
1. Type of Well □ Gas Well □ Other Image: Contract of the state of the sta				8. Well Name and No.		
. Name of Operator Hunt Cimar				Cedar Point 14-L Federal No. 1 9. API Well No. 30-005-29153 10. Field and Pool, or Exploratory Area		
a. Address P.O. Box 1592, Roswell, New M	3b. Phone No. (include a 575-623-9799					
Location of Well (Footage, Sec.,		1		10. Field ar	nd Pool, or Exploratory Area	
1980' FSL & 660' FWL, Section 14, T 15-S, R 30-E, NMPM					11. County or Parish, State	
		,		Chave	s County, New Mexico	
12. CHECK A	PPROPRIATE BOX(ES) T	O INDICATE NATURE	OF NOTICE,	REPORT, O	R OTHER DATA	
TYPE OF SUBMISSION		ТҮРІ	E OF ACTION	· · · ·		
	Acidize	Deepen	Production	(Start/Resume)	Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat			Well Integrity	
Subsequent Report	Casing Repair	New Construction Plug and Abandon	Recomplete	Abandon	cement casing	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dispo			
determined that the site is read	y for final inspection) e bottom plug to TD 7-7/8" h	ole at 9500' at 9:00 am				
	# casing to 9488' with DV too		n 1025 sacks in 2	stages as follow	vs: 1st stage lead with 270 sx	
10/9/2012: Ran 5-1/2, 17# 50/50 Poz C and tail with	315 sx H. 2nd stage lead wit	l at 6212'. Cemented with h 240 sx 50/50 Poz C and	tail with 200 sx	С.	_	
10/9/2012: Ran 5-1/2, 17# 50/50 Poz C and tail with		l at 6212'. Cemented with h 240 sx 50/50 Poz C and	tail with 200 sx	С.	-	
10/9/2012: Ran 5-1/2, 17# 50/50 Poz C and tail with	315 sx H. 2nd stage lead wit	l at 6212'. Cemented with h 240 sx 50/50 Poz C and	tail with 200 sx	С.	-	
10/9/2012: Ran 5-1/2, 17# 50/50 Poz C and tail with	315 sx H. 2nd stage lead wit	l at 6212'. Cemented with h 240 sx 50/50 Poz C and	tail with 200 sx	С.	-	
10/9/2012: Ran 5-1/2, 17# 50/50 Poz C and tail with	315 sx H. 2nd stage lead wit	l at 6212'. Cemented with h 240 sx 50/50 Poz C and	tail with 200 sx	С.	-	
10/9/2012: Ran 5-1/2, 17# 50/50 Poz C and tail with	315 sx H. 2nd stage lead wit	l at 6212'. Cemented with h 240 sx 50/50 Poz C and	tail with 200 sx	С.	-	
10/9/2012: Ran 5-1/2, 17 50/50 Poz C and tail with 10/10/2012: Plug down or	315 sx H. 2nd stage lead wit n 2nd stage at 3:02 am. Rele	l at 6212'. Cemented with h 240 sx 50/50 Poz C and	tail with 200 sx	С.	-	
10/9/2012: Ran 5-1/2, 17 50/50 Poz C and tail with 10/10/2012: Plug down or 10/10/2012: Angle down or 14. Thereby certify that the for- Name (<i>Printed/Typed</i>)	315 sx H. 2nd stage lead wit n 2nd stage at 3:02 am. Relea egoing is true and correct	l at 6212'. Cemented with h 240 sx 50/50 Poz C and ase and begin to move our	tail with 200 sx t Silver Oak Rig	С.	-	
10/9/2012: Ran 5-1/2, 17 50/50 Poz C and tail with 10/10/2012: Plug down of 14. I hereby certify that the for	315 sx H. 2nd stage lead wit n 2nd stage at 3:02 am. Relea egoing is true and correct	l at 6212'. Cemented with h 240 sx 50/50 Poz C and ase and begin to move our	tail with 200 sx	С.	-	
10/9/2012: Ran 5-1/2, 174 50/50 Poz C and tail with 10/10/2012: Plug down of 14. Ihereby certify that the formore (Printed/Typed) Richard C. Gilling Signature	315 sx H. 2nd stage lead wit n 2nd stage at 3:02 am. Relea egoing is true and correct	l at 6212'. Cemented with h 240 sx 50/50 Poz C and ase and begin to move our	tail with 200 sx t Silver Oak Rig	С.	-	
10/9/2012: Ran 5-1/2, 17 50/50 Poz C and tail with 10/10/2012: Plug down of 14. Ihereby certify that the for Name (<i>Printed/Typed</i>) Richard C. Gilli	315 sx H. 2nd stage lead wit n 2nd stage at 3:02 am. Rele: egoing is true and correct iland	l at 6212'. Cemented with h 240 sx 50/50 Poz C and ase and begin to move out ase and begin to move out	tail with 200 sx t Silver Oak Rig ce President	C. #8. Prepare to 10/15/2012	-	
10/9/2012: Ran 5-1/2, 174 50/50 Poz C and tail with 10/10/2012: Plug down of 14. Ihereby certify that the formore (Printed/Typed) Richard C. Gilling Signature	315 sx H. 2nd stage lead wit n 2nd stage at 3:02 am. Rele: egoing is true and correct iland	at 6212'. Cemented with h 240 sx 50/50 Poz C and ase and begin to move our Title Vi Date R FEDERAL OR ST	tail with 200 sx t Silver Oak Rig ce President	C. #8. Prepare to 10/15/2012 CE USE	move in completion unit.	
10/9/2012: Ran 5-1/2, 17 50/50 Poz C and tail with 10/10/2012: Plug down of 14. Ihereby certify that the for- Name (<i>Printed/Typed</i>) Richard C. Gilli Signature ACCEPTED Approved by Conditions of approval, if any, are certify that the applicant holds leg	315 sx H. 2nd stage lead wit n 2nd stage at 3:02 am. Relea egoing is true and correct iland POTHIS SPACE FOR IPOR GLAS attached. Approval of this notic al, or equitable stille to those right	I at 6212'. Cemented with h 240 sx 50/50 Poz C and ase and begin to move out Trile Vi Date R FEDERAL OR ST SS Trile vi Trile vi Date	tail with 200 sx t Silver Oak Rig ce President ΓΑΤΕ OFFIC	C. #8. Prepare to 10/15/2012 CE USE	move in completion unit.	
10/9/2012: Ran 5-1/2, 17 50/50 Poz C and tail with 10/10/2012: Plug down of 14. Ihereby certify that the for- Name (Printed/Typed) Richard C. Gilli Signature ACCEPTED Approved by Conditions of approval, if any, are certify that the applicant holds leg which would entitle the applicant	315 sx H. 2nd stage lead wit n 2nd stage at 3:02 am. Relea egoing is true and correct iland POHIS SPACE FOR DOR. GLAS attached. Approval of this notice attached. Approval of the attached. Approval of the	I at 6212'. Cemented with h 240 sx 50/50 Poz C and ase and begin to move out Title Vi Date R FEDERAL OR ST SS Title subject lease Title subject lease	tail with 200 sx t Silver Oak Rig ce President FATE OFFIC tle	C. #8. Prepare to 10/15/2012 CE USE ROSWEL	move in completion unit.	

OCT 2.9 2012

م من

. . .

•

•