

Submit 3 Copies To Appropriate District Office
District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Ave , Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-28551
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/> FED X
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name HARRIS FEDERAL
8. Well Number #1
9. OGRID Number 3474
10. Pool name or Wildcat SWD: DELAWARE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other -SWD ☒ **HOBBS OCD**

2. Name of Operator
STATE OF NEW MEXICO formerly CW TRAINER

3. Address of Operator
1625 N. FRENCH DRIVE HOBBS, NM 88240

4. Well Location
Unit Letter O : 660 feet from the SOUTH line and 1980 feet from the EAST line
Section 5 Township 22S Range 34E NMPM LEA County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: 10/31/2012 Amended ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

13 3/8" csg set at 1120'—cmt w/900 sxs, circ
10 3/4" csg set at 4800'---cmt w/1400 sxs, circ
7 5/8" csg set at 11,800'—cmt w/450 sxs, DV TOOL at 8428' 2nd stage cmt, toc est 1800'. 1146'-50' Sqz w/100 sxs cmt.
Perfs 5790'-6011' PBTd-9100' TD 14,054'

Tag CIBP at 9100'. Circ MLF. Cap w/25 sxs cmt. Spot 35 sx cmt at 6300'. Set 7 5/8" CIBP at 5750', cap w/25 sxs cmt.
Spot 50 sxs cmt at 4850'. WOC and TAG. Spot 50 sxs cmt at 3570'. Spot 50 sxs cmt at 1650'.
Perf at 1171'. Sqz 50 sxs cmt. WOC and TAG. Perf at 300', circ cmt iside and out to surface.
Cutoff anchors and wellhead. Install dryhole marker.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Maley Shawn

TITLE

Compliance Officer

DATE

10/31/2012

Type or print name

E-mail address:

PHONE:

For State Use Only

APPROVED BY:

[Signature]

TITLE

DIST. MGR

DATE

10-31

Conditions of Approval (if any):

OCT 31 2012