Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II HOBBS O	OIL CONSERVATION DIVISION	WELL API NO. 30-025-22108
1301 W. Grand Ave , Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87AUG 1 5 2 District IV	Santa Fe, NM 87505	STATE FEE Z
District IV AUG I O C 1220 S. St Francis Dr., Santa Fe, NM 87505	Santa Fe, INIVI 87505	6. State Oil & Gas Lease No. 26537
SUNDRY NOTECER/	D REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.)	O DRILL OR TO DEEPEN OR PLUG BACK TO A FOR PERMIT" (FORM C-101) FOR SUCH	JFG COLLIER
1. Type of Well: Oil Well 🔽 Gas W	/ell 🗖 Other	8. Well Number 1 9. OGRID Number 247602
J. Name of Operator	AY MANAGEMENT CO., LLC 🖊	9. OOKID Number 247692
3. Address of Operator 2425 WEST LO	OP SOUTH - STE 810; HOUSTON, TX 77027	10. Pool name or Wildcat BAGLEY PERMO PENN, NORTH
4. Well Location	······································	
Unit Letter D : 66		810 feet from the WEST line
Section 9	Township 11S Range 33E	NMPM County LEA
11.1	Elevation (Show whether DR, RKB, RT, GR, e GL 4302'	tc.)
12. Check Appro	priate Box to Indicate Nature of Notic	e, Report or Other Data
•••	• 	-
NOTICE OF INTEN PERFORM REMEDIAL WORK D PLU	G AND ABANDON 🔲 REMEDIAL WO	BSEQUENT REPORT OF: DRK 20 ALTERING CASING 2
	_	RILLING OPNS. PANDA
DOWNHOLE COMMINGLE		·
OTHER:		
13. Describe proposed or completed o	perations. (Clearly state all pertinent details, EE RULE 19.15.7.14 NMAC. For Multiple C	and give pertinent dates, including estimated dat Completions: Attach wellbore diagram of
Well-was re-entered and work was	done as per the attached daily summary. N	Io casing lk was found. Had small leak off
between 6130' - 6774'. Could not	stablish any rate into interval and "Negativ	e test" by swab indicated no fluid entry
from this interval. Well was return	ed to production. 8/05/2011	
	0,00,00	
Spud Date:	Rig Release Date: 05	-AUGUST-2011
L		
I hereby certify that the information above	is true and complete to the best of my knowle	dge and belief.
ì	0	
SIGNATURE FOR ALL	TITLE SENIOR STAFF	ENGINEER DATE 10-AUGUST-2011
Type or print name RON GILBRE	ATH E-mail address: rgilbreath@is	ramco.jay.com PHONE: 713/456-7892 Ext 3
For State Use Only	1	
APPROVED BY: Sum	TITLE DET MA	DATE /1-8-20
Conditions of Approval (if any):	~	
		/

• 1

L

NON	Q	8	2042	
NON	Q	8	2012	

	Jay Management Company		
	2425 West Loop South, Ste 82	10	
	Houston, TX 77027		
	Daily Workover Report of Opera	itions	
Well Name:	JFG COLLIER No 1	AFE #:	0
Field Name:	BAGLELY PERMO PENN, NORRTH	County:	LEA-NEW N
Begin Date:	1-Aug-2011	End Date:	8-A
	Monday, August 01, 2011		
MI RU PU. ND WH & NI and scraper. SDFN.	U BOPS. PU & RIH w/ 285 jts 2 3/8" tubing (9164.46') w/	bit and scraper. POOH & stoo	d tbg in derricl
Daily Cost:	\$0.00	Cum Cost:	
	Tuesday, August 02, 2011		
PU RBP & PKR. RIH. &	set pkr @ 9097'. Waited on pmp trk. NO show. SDFN		
Daily Cost:	\$0.00	Cum Cost:	
	Wednesday, August 03, 2011		
Deile Ceet			
Daily Cost:	\$0.00	Cum Cost:	
SITP = 0 psi. RU & RIH POOH. Moved RBP to 9	Thursday, August 04, 2011 w/ swab. BFL @ 3300' FS. Swabbed to SN. SD for 1 hr. N '220'. Perfs 9206-10' & 9192 - 99'. Set RBP & "got off". PU	o entry. Unset pkr & RIH to R	
SITP = 0 psi. RU & RIH POOH. Moved RBP to 9 Swaabbed to SN recove	Thursday, August 04, 2011 w/ swab. BFL @ 3300' FS. Swabbed to SN. SD for 1 hr. N 220'. Perfs 9206-10' & 9192 - 99'. Set RBP & "got off". PU ring approx 1000' each run. SDFN	o entry. Unset pkr & RIH to R I pkr to 9093' & set. RU to sw	
SITP = 0 psi. RU & RIH POOH. Moved RBP to 9	Thursday, August 04, 2011 w/ swab. BFL @ 3300' FS. Swabbed to SN. SD for 1 hr. N 220'. Perfs 9206-10' & 9192 - 99'. Set RBP & "got off". PU ring approx 1000' each run. SDFN \$0.00	o entry. Unset pkr & RIH to R	
SITP = 0 psi. RU & RIH POOH. Moved RBP to 9 Swaabbed to SN recove Daily Cost: RU to swab. BFL @ 890	Thursday, August 04, 2011 w/ swab. BFL @ 3300' FS. Swabbed to SN. SD for 1 hr. N 220'. Perfs 9206-10' & 9192 - 99'. Set RBP & "got off". PU ering approx 1000' each run. SDFN \$0.00 Friday, August 05, 2011 00' FS. Swabbed well to SN is 6 run. SD for 1 hr. No entry.	o entry. Unset pkr & RIH to R I pkr to 9093' & set. RU to sw Cum Cost:	ab perfs. BFL (
SITP = 0 psi. RU & RIH POOH. Moved RBP to 9 Swaabbed to SN recove Daily Cost: RU to swab. BFL @ 890 BP & POOH. LD BP. SD	Thursday, August 04, 2011 w/ swab. BFL @ 3300' FS. Swabbed to SN. SD for 1 hr. N 2220'. Perfs 9206-10' & 9192 - 99'. Set RBP & "got off". PU ering approx 1000' each run. SDFN \$0.00 Friday, August 05, 2011 20' FS. Swabbed well to SN is 6 run. SD for 1 hr. No entry. FN.	o entry. Unset pkr & RIH to R I pkr to 9093' & set. RU to swa Cum Cost: RD swab. Unset pkr & RIH to	ab perfs. BFL (
SITP = 0 psi. RU & RIH POOH. Moved RBP to 9 Swaabbed to SN recove Daily Cost: RU to swab. BFL @ 890	Thursday, August 04, 2011 w/ swab. BFL @ 3300' FS. Swabbed to SN. SD for 1 hr. N 9220'. Perfs 9206-10' & 9192 - 99'. Set RBP & "got off". PU ering approx 1000' each run. SDFN \$0.00 Friday, August 05, 2011 00' FS. Swabbed well to SN is 6 run. SD for 1 hr. No entry. FN. \$0.00	o entry. Unset pkr & RIH to R I pkr to 9093' & set. RU to sw Cum Cost:	ab perfs. BFL (
SITP = 0 psi. RU & RIH POOH. Moved RBP to 9 Swaabbed to SN recove Daily Cost: RU to swab. BFL @ 890 BP & POOH. LD BP. SD	Thursday, August 04, 2011 w/ swab. BFL @ 3300' FS. Swabbed to SN. SD for 1 hr. N 2220'. Perfs 9206-10' & 9192 - 99'. Set RBP & "got off". PU ering approx 1000' each run. SDFN \$0.00 Friday, August 05, 2011 20' FS. Swabbed well to SN is 6 run. SD for 1 hr. No entry. FN.	o entry. Unset pkr & RIH to R I pkr to 9093' & set. RU to swa Cum Cost: RD swab. Unset pkr & RIH to	ab perfs. BFL (
SITP = 0 psi. RU & RIH POOH. Moved RBP to 9 Swaabbed to SN recove Daily Cost: RU to swab. BFL @ 890 BP & POOH. LD BP. SD Daily Cost:	Thursday, August 04, 2011 w/ swab. BFL @ 3300' FS. Swabbed to SN. SD for 1 hr. N 9220'. Perfs 9206-10' & 9192 - 99'. Set RBP & "got off". PU ering approx 1000' each run. SDFN \$0.00 Friday, August 05, 2011 00' FS. Swabbed well to SN is 6 run. SD for 1 hr. No entry. FN. \$0.00	o entry. Unset pkr & RIH to R I pkr to 9093' & set. RU to swa Cum Cost: RD swab. Unset pkr & RIH to	ab perfs. BFL (
SITP = 0 psi. RU & RIH POOH. Moved RBP to 9 Swaabbed to SN recove Daily Cost: RU to swab. BFL @ 890 BP & POOH. LD BP. SD Daily Cost: 0 Daily Cost:	Thursday, August 04, 2011 w/ swab. BFL @ 3300' FS. Swabbed to SN. SD for 1 hr. N '220'. Perfs 9206-10' & 9192 - 99'. Set RBP & "got off". PU ering approx 1000' each run. SDFN \$0.00 Friday, August 05, 2011 00' FS. Swabbed well to SN is 6 run. SD for 1 hr. No entry. FN. \$0.00 Saturday, August 06, 2011	o entry. Unset pkr & RIH to R l pkr to 9093' & set. RU to swa Cum Cost: RD swab. Unset pkr & RIH to Cum Cost:	ab perfs. BFL (
SITP = 0 psi. RU & RIH POOH. Moved RBP to 9 Swaabbed to SN recove Daily Cost: RU to swab. BFL @ 890 BP & POOH. LD BP. SD Daily Cost:	Thursday, August 04, 2011 w/ swab. BFL @ 3300' FS. Swabbed to SN. SD for 1 hr. N 220'. Perfs 9206-10' & 9192 - 99'. Set RBP & "got off". PU ering approx 1000' each run. SDFN \$0.00 Friday, August 05, 2011 00' FS. Swabbed well to SN is 6 run. SD for 1 hr. No entry. FN. \$0.00 Saturday, August 06, 2011 \$0.00	o entry. Unset pkr & RIH to R l pkr to 9093' & set. RU to swa Cum Cost: RD swab. Unset pkr & RIH to Cum Cost:	ab perfs. BFL (
SITP = 0 psi. RU & RIH POOH. Moved RBP to 9 Swaabbed to SN recove Daily Cost: RU to swab. BFL @ 890 BP & POOH. LD BP. SD Daily Cost: 0 Daily Cost:	Thursday, August 04, 2011 w/ swab. BFL @ 3300' FS. Swabbed to SN. SD for 1 hr. N 220'. Perfs 9206-10' & 9192 - 99'. Set RBP & "got off". PU ering approx 1000' each run. SDFN \$0.00 Friday, August 05, 2011 00' FS. Swabbed well to SN is 6 run. SD for 1 hr. No entry. FN. \$0.00 Saturday, August 06, 2011 \$0.00	o entry. Unset pkr & RIH to R l pkr to 9093' & set. RU to swa Cum Cost: RD swab. Unset pkr & RIH to Cum Cost:	ab perfs. BFL (
SITP = 0 psi. RU & RIH POOH. Moved RBP to 9 Swaabbed to SN recove Daily Cost: RU to swab. BFL @ 890 BP & POOH. LD BP. SD Daily Cost: 0 Daily Cost: SF FOR SUNDAY	Thursday, August 04, 2011 w/ swab. BFL @ 3300' FS. Swabbed to SN. SD for 1 hr. N 220'. Perfs 9206-10' & 9192 - 99'. Set RBP & "got off". PU ering approx 1000' each run. SDFN \$0.00 Friday, August 05, 2011 00' FS. Swabbed well to SN is 6 run. SD for 1 hr. No entry. FN. \$0.00 Saturday, August 06, 2011 \$0.00 \$0.00 \$0.00	o entry. Unset pkr & RIH to R pkr to 9093' & set. RU to swa Cum Cost: RD swab. Unset pkr & RIH to Cum Cost: Cum Cost:	ab perfs. BFL (
SITP = 0 psi. RU & RIH POOH. Moved RBP to 9 Swaabbed to SN recove Daily Cost: RU to swab. BFL @ 890 BP & POOH. LD BP. SD Daily Cost: 0 Daily Cost: SF FOR SUNDAY Daily Cost: Checked well. OK. RD N	Thursday, August 04, 2011 w/ swab. BFL @ 3300' FS. Swabbed to SN. SD for 1 hr. N 220'. Perfs 9206-10' & 9192 - 99'. Set RBP & "got off". PU ring approx 1000' each run. SDFN \$0.00 Friday, August 05, 2011 00' FS. Swabbed well to SN is 6 run. SD for 1 hr. No entry. FN. \$0.00 \$0.00 \$0.00 \$0.00 Saturday, August 06, 2011	o entry. Unset pkr & RIH to R pkr to 9093' & set. RU to swa Cum Cost: RD swab. Unset pkr & RIH to Cum Cost: Cum Cost:	ab perfs. BFL (
SITP = 0 psi. RU & RIH POOH. Moved RBP to 9 Swaabbed to SN recove Daily Cost: RU to swab. BFL @ 890 BP & POOH. LD BP. SD Daily Cost: 0 Daily Cost: SF FOR SUNDAY Daily Cost: Checked well. OK. RD N	Thursday, August 04, 2011 w/ swab. BFL @ 3300' FS. Swabbed to SN. SD for 1 hr. N 220'. Perfs 9206-10' & 9192 - 99'. Set RBP & "got off". PU ering approx 1000' each run. SDFN \$0.00 Friday, August 05, 2011 00' FS. Swabbed well to SN is 6 run. SD for 1 hr. No entry. FN. \$0.00 Saturday, August 06, 2011 \$0.00 \$0.00 Sunday, August 07, 2011 \$0.00 Monday, August 08, 2011 MO PU. WELL HAS A SMALL LK OFF BETWEEN 6130' - 670	o entry. Unset pkr & RIH to R pkr to 9093' & set. RU to swa Cum Cost: RD swab. Unset pkr & RIH to Cum Cost: Cum Cost:	ab perfs. BFL (



## **ISRAMCO - JAY MANAGEMENT**

CURRENT COMPLETION

