Submit 1 Copy To Appropriate District Office  HOBBS C	State of New Me		Form C-103 Revised August 1, 2011
District 1 – (575) 393-6161  1625 N. French Dr., Hobbs, NM 88240  HOBBS QCD, Minerals and Natural Resources		WELL API NO.	
District 11 - (575) 748-1283 811 S. First St., Artesia, NM 88210 OCI - OLUZONSERVATION DIVISION			30-025-0/27/
<u>District III</u> – (505) 334-6178 1220 South St. Francis Dr.			5. Indicate Type of Lease STATE ▼ FEE □
1000 Rio Brazos Rd , Aztec, NM 87410 <u>District IV</u> – (505) 476-3460  RECEIVED  Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S St. Francis Dr , Santa Fe, MA 87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Phillips State
PROPOSALS.)  1. Type of Well: Oil Well  Gas Well  Other		8. Well Number	
2. Name of Operator  STAR OIL & GAS COMPANY		9. OGRID Number 26 9 8 3 9	
3. Address of Operator 4008 N. GRIMES #137, HUBBS, NM 88240		10. Pool name or Wildcat	
4. Well Location		Kemnitz Wolfcamp	
Unit Letter I: 1980 feet from the See the line and 660 feet from the East line			
Section 25 Township /6S Range 33 E NMPM County LEA			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK			<del></del>
TEMPORARILY ABANDON			<del>-</del>
PULL OR ALTER CASING			I JOB []
<u> </u>			
OTHER: KE-ENTRY  OTHER: OTHER:  OTHER: OTHER:  OTHER: OTHER:  OTHER: OTHER:  OTHER: OTHER:  OTHER: OTHER: OTHER:			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
1. INSTALL, REMOVE DRY HOLE MARKER			
2. DIG OLD CELLAR, INSTALL WELL HEAD.			
3. RU JWS. NU BOP & TEST SAME			
4. DRILL COMENT PLUGS @ SURFACE, 4/15, 1700 & 4400 +.			
5. TEST CASING ABOVE THE CLBP & CMT PLUG @ 10,725.			
6 Seil per CIBP, CIRC. HOLE CLEAN TO BELOW "			
TO ALL CLINEILE ASSEMBLE			
9. ACIDIZE W) BOOK GAL. IF NECESSARY.  10. PUT ON PRODUCTION.			
10. PUT ON PRODUCTION.			
		i	
Spud Date:	Rig Release Da	ite:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
$\ell$			
SIGNATURE Saphyfflire TITLE President DATE 10-10-12			
Type or print name <u>Sie Phen J Mave</u> E-mail address: <u>SJ NAVAC CMAIL COR</u> HONE: <u>575-631-9518</u> For State Use Only			
The state of the s			
Conditions of Approval (if any):			
NOV 1 4 2012			
			MOA .