Oil Conservation Division - Hobbs office. Must be Notified 24 hours prior to the beginning of Plugging Operations begin

| 1 | · AMARCINE | 7 | NA VEL AI NUC |
|------|---|--|------------------------|
| | WELL BORE INFO. | The second second | |
| 0 | | | |
| 367 | | | |
| 734 | 11 1/4" Hole | TO THE PROPERTY OF THE PROPERT | |
| 1101 | 8 5/8" 24# @ 1070' w/ 800 sx cmt to surf | The second secon | |
| 1468 | | See the second s | |
| 1836 | | THE PROPERTY OF THE PROPERTY O | |
| 2203 | TOC @ | 2375' | |

2 3/8" tbg w/ Lok-set pkr & on/off tool @ 3365'

6 3/4" Hole 4 1/2" 11.6# @ 3671' w/ 800 sx cmt TOC @ 2375'

2570

2937

3304

3671

Queen perfs @ 3444' - 3618'

PBTD @ 3642' TD @ 3671'

| WELL BORE INFO. |
|-----------------|
| |

0

1468

1836

2203

2570

3304

3671

| New Mexico BZ State NCT-8 | |
|---------------------------|--|
| 3 | |
| 30-025-10761 | |
| Lea | |
| | |

PROPOSED PROCEDURE 5 PUH & perf @ 200' & sqz 75 sx Class "C" cmt from 200' to surf (Water Board) 4. PUH & perf @ 1120' & sqz 50 sx Class "C" cmt from 1120' -1020' WOC/TAG (Top of Salt & Shoe) 3 PUH & perf @ 2400', RIH w/ tbg to 2600' & spot 40 sx Class "C" cmt , PUH & sqz cmt to 2350' WOC/TAG (Yates & Base of 2. MIRU P&A rig, RIH w/ tbg & CIRC w/ MLF, & spot 25 sx Class 'C" cmt from 3400'-3000' WOC/TAG (CIBP, QN & 7 Rvrs) 1. MIRU service rig and remove tbg & pkr RIH & set CIBP @ 3400' w/ no cmt RDMO service rig Queen perfs @ 3444' - 3618'

734

11 1/4" Hole
8 5/8" 24# @ 1070'
w/ 800 sx cmt to surf

TOC @ 2375'

2937

2 3/8" tbg w/ Lok-set pkr & on/off tool @ 3365'

PBTD @ 3642' TD @ 3671'

6 3/4" Hole 4 1/2" 11.6# @ 3671' w/ 800 sx cmt TOC @ 2375'