

HOBBS OCD

State of New Mexico  
Energy, Minerals and Natural Resources DepartmentForm C-103  
Revised 5-27-2004

FILE IN TRIPLICATE

NOV 16 2012

## OIL CONSERVATION DIVISION

## DISTRICT I

1625 N French Dr., Hobbs, NM 88240

## DISTRICT II

1301 W. Grand Ave, Artesia, NM 88210

## DISTRICT III

1000 Rio Brazos Rd, Aztec, NM 87410

1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

WELL API NO

30-025-07417

5. Indicate Type of Lease

STATE ☐FEE ☒

6. State Oil &amp; Gas Lease No.

7. Lease Name or Unit Agreement Name

North Hobbs (G/SA) Unit  
Section 28

8. Well No 311

9. OGRID No 157984

10. Pool name or Wildcat Hobbs (G/SA)

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)

1. Type of Well

Oil Well ☐Gas Well ☐Other ☒ Temporarily Abandoned

2. Name of Operator

Occidental Permian Ltd.

3. Address of Operator

HCR 1 Box 90 Denver City, TX 79323

4. Well Location

Unit Letter B

1315

Feet From The

North

Line and

2310

Feet From The

East

Line

Section 28

Township 18-S

Range 38-E

NMPM

Lea

County

11. Elevation (Show whether DF, RKB, RT GR, etc)  
3650' DFPit or Below-grade Tank Application ☐or Closure ☐

Pit Type \_\_\_\_\_ Depth of Ground Water \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water

Pit Liner Thickness \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐CHANGE PLANS ☐PULL OR ALTER CASING ☐Multiple Completion ☐

OTHER: \_\_\_\_\_

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐PLUG & ABANDONMENT ☐CASING TEST AND CEMENT JOB ☐OTHER: MIT failure repair/TA status request ☒

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RUPU &amp; RU.

2. ND wellhead/NU BOP

3. POOH w/tubing and packer.

4. RIH w/CIBP set @3995'. Tested plug &amp; casing to 550 PSI. Tested good.

5. RU wireline and dump 7 sacks of cement on top of CIBP. Tagged TOC at 3958'. RD wireline.

6. Test casing to 575 PSI for 30 minutes and chart for the NMOCD.

7. ND BOP/NU TA wellhead.

8. RDPU &amp; RU. Clean location and leave well in TA status.

This Approval of Temporary  
Abandonment Expires

9-21-2017

RUPU 09/17/2012

RDPU 09/21/2012

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or

closed according to NMOCD guidelines ☐, a general permit ☐or an (attached) alternative OCD-approved plan ☐

SIGNATURE

Mendy A. Johnson

TITLE

Administrative Associate

DATE

11/14/2012

TYPE OR PRINT NAME

Mendy A. Johnson

E-mail address:

mendy\_johnson@oxy.com

TELEPHONE NO

806-592-6280

For State Use Only

APPROVED BY

TITLE


DST. MGR

DATE

11-19-2012


CONDITIONS OF APPROVAL IF ANY:

NOV 19 2012



November 13, 2012

## Work Plan Report for Well:NHSAU 311-28



Survey Viewer