Summit 3 Copies 10 Appropriate District Office	State of New Mexico		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-09408 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			State A A/C 1
1. Type of Well: Oil Well Gas Well Other			8. Well Number # 51
2. Name of Operator Mission Resources			9. OGRID Number
3. Address of Operator			10. Pool name or Wildcat Langlie Mattix 7
1331 Lamar, Suite 1455, Houston TX 77010-3039			Rvrs Qn GB
4. Well Location			
	feet from the		
Section 24	Township	23S Range 36	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3358' KB			
Pit or Below-grade Tank Application O			
	terDistance from neares		stance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN	TENTION TO:	SUE	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			RK ALTERING CASING
TEMPORARILY ABANDON PULL OR ALTER CASING	_		ILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL [CASING/CEMEN	IT JOB L
OTHER:		OTHER:	
 Describe proposed or compl of starting any proposed wo or recompletion. 	eted operations. (Clearly stark). SEE RULE 1103. For	ate all pertinent details, ar Multiple Completions: A	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
1 Set 5 1/2 CIDD @ 1002 1/	h 6 O 25001		181920212222
1. Set 5 ½" CIBP @ 100' +/- above top perf @ 3508'.			
2. Circulate hole w/ packer fluid & KCL.			
2. Circulate hole w/ packer fluid & KCL. 3. Test casing to 500 psig for 30 minutes.			
4 Call OCD 8 along 40 1			(E) 6)
4. Call OCD & give 48 hrs not	ice to T/A Status Test. (Rec	ord test on chart for subs	equent report.)
4. Call OCD & give 48 hrs not	ice to T/A Status Test. (Rec	cord test on chart for subs	equent report.)
4. Call OCD & give 48 hrs not	ice to T/A Status Test. (Rec	cord test on chart for subs	equent report.)
4. Call OCD & give 48 hrs not	ice to T/A Status Test. (Rec	ord test on chart for subs	equent report.)
4. Call OCD & give 48 hrs not	ice to T/A Status Test. (Red	ord test on chart for subs	equent report.)
			equent report.)
I hereby certify that the information a	above is true and complete to	o the best of my knowled	re and belief. I further certify that any pit or below.
I hereby certify that the information a grade tank has been/will be constructed or o	above is true and complete to closed according to NMOCD guid	o the best of my knowledg lelines □, a general permit □	equent report.) The equent report. The equen
I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE	above is true and complete to	o the best of my knowledgelines □, a general permit □	equent report.) see and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE Type or print name Joel Sisk	above is true and complete to closed according to NMOCD guid	o the best of my knowledg lelines □, a general permit □	ge and belief. I further certify that any pit or below- lor an (attached) alternative OCD-approved plan
I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE	above is true and complete to closed according to NMOCD guide TITE E-mail address	o the best of my knowleds lelines , a general permit . LE Sr. Production To	ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE Type or print name Joel Sisk For State Use Only APPROVED BY:	above is true and complete to closed according to NMOCD guide TITE E-mail address	o the best of my knowledgelines □, a general permit □	ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 5-23-2005
I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE Type or print name Joel Sisk For State Use Only	above is true and complete to closed according to NMOCD guide TITE E-mail address	o the best of my knowleds lelines , a general permit . LE Sr. Production To	ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 5-23-2005

Mission Resources Corp. State A A/C-1 #51 Jalmat Field Lea County, NM

May 20, 2005

Temporary Abandonment Procedure

- 1. MIRU work over rig. Pull rods laying down.
- 2. ND tree & NU BOPs. POH with tubing.
- 3. PU 5-1/2" casing scraper & RIH with tubing to 3450'. POH.
- 4. PU 5-1/2" CIBP and RIH and set at 3450'.
- 5. Circulate hole with packer fluid and KCl.
- 6. Test casing to 500 psig for 30 minutes.
- 7. Pull & lay down tubing. ND BOPs.
- 8. Call OCD & give 48 hrs notice for T/A Status Test. (Record test on chart for subsequent report.)

