State of New Mexico Oil Conservation Division, Disposervation Submit 3 Copies to Appropriate finerals and Natural Resources Department. French Drive District Office Bureau of Land Managements. NM 88240 **DISTRICT I** OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs, NM 88240 WELL API NO. 2040 Pacheco St. Santa Fe. NM 87505 30-025-25164 P.O. Drawer DD, Artesia, NM 88210 sIndicate Type of Lease 100 Federal STATE DISTRICT III FEE 1000 Rio Brazos Rd., Aztec, NM 87410 State Oil & Gas Lease No. NMLCOL7982B SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) McKay Shell Type of Well: WELL WELL X OTHER 2Name of Operator «Well No. Ray Westall Operating 3Address of Operator Pool name or Wildcat P. O. Box 4, Loco Hills, New Mexico 88255 4Well Location 2310' Feet From The _ Feet From The Section Township County Lea **NMPM** »Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON PERFORM REMEDIAL WORK REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ANBANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER: OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed 06/29/04 Set 5 1/2 CIBP @ 12575. Circulate hole with mud laiden fluid. Spot 25 sx class "H" cmt on top CIBP. 06/30/04 Spot 200 ft. cmt plug @ 10500. WOC 4 hours. Tag plug @ 10208. POH to 10000 ft. Spot 25 sx plug Class "H" cmt. POH 60 07/01/04 Tag plug @ 9809. POOH w/ tbg. RIH w/ wire line, perferate 5 1/2 csg. @ 6400'. POOH w/ W. L. SDFN 07/02/04 RIH w/ PKR> to 6093 Pressure up on casing. Did not hold. POOH w/ PKR. . RIH w/ tbg. to 6450 Spot 25 sx class "C" neat cmt. POOH w/ tbg.. RIH with PKR to 60 fett. Pressure up to 1000 PSI. SDFN 07/06/04 RIH with W. L. to 6600'. Din not tag plug. POOH w/ W. L. RIH with tbg. to 6450, spot 25 sx class "C" neat cmt POOH w/ 60 jts. 07/07/04 RIH w/ tbg. Tag plug @ 6313' POOH w/ tbg. RIH with W. L. Perf. csg @ 4180'. POH w/ W. L. RIH w/ tbg & PKR. Set PKR @ 3894 SQZ. 25 sx class "C" neat cmt. displace to 4080'. Closed well in SDFN. 07/08/04 Tag plug @ 4068. POOH w/ tbg. RIH w/ W. L. Perf. csg. @ 1350". RIH w/ and set PKR @ 1067'. SQZ. 65 sx class "C" neat cmt.to 1250. WOC 4hours. Tag plug "@ 1280'. POOH w/tbg. RIH w/ W. L. Perf. csg. @ 420 feet. ND BOP flange up 5 1/2 head. SDFN. 07/09/04 Pumped cmt. and circulated to surface. WOC 2 hours. Pumped 30 foot surface plug. dug out well head Install Dry Hole Marker ACCEPTED FOR RECORD I hereby certify that the information above is true and complete to the best of my knowledge and belief. accounting SIGNATURE MAY ZATE 2005/19/04 TITLE TYPE OR PRINT NAME OE FIELD REPRESENTATIVE II/STAFF WANAGE (This space for State Use)