Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-32140
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE XXX 6. State Oil & Gas Lease No.
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa 1 C, 14141 07303	6. State Oil & Gas Lease No.
87505		
	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		RHINO
1. Type of Well: Oil Well Gas Well XXXX Other		8. Well Number 1
2. Name of Operator		9. OGRID Number 3659
CAPATAZ OPERATING, INC		
3. Address of Operator		10. Pool name or Wildcat
PO BOX 10549, MIDLAND, TX	79702	SOUTHWEST HOUSE – YSR GAS
4. Well Location		
Unit Letter N :	660 feet from the S line and	1980 feet from theWline
Section 11	Township 20S Range 39E	
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
	3595 KB	
Pit or Below-grade Tank Application 🔲	or Closure 🗌	
Pit typeSTEEL PITDepth to Gro	undwater_49'_Distance from nearest fresh water well_1/4 MIL	E Distance from nearest surface water_NONE
Pit Liner Thickness: mil	Below-Grade Tank: Volumebbls; (Construction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
12. Check Appropriate Box to indicate Nature of Notice, Report of Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON XXX REMEDIAL WO	RK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DE	RILLING OPNS.□ P AND A □
PULL OR ALTER CASING	MULTIPLE COMPL	NT JOB
	_	_
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.		
Steel Pit will be used 300		
Surface Casing: 8-5/8" @ 21182 – circulated to Surface. T.O.S.(Top of Salt) 1700' Est; B.O.S.(Bottom of Salt) 2800'2		
Snot 100' nlug F/368' 268' or 25 SV whichever is greater. Tog		
Production Basing: 5-1/2" to 3053' Circulated to Surface		
Production Basing: 5-1/2" to 3053' Circulated to Surface Open Hole 3053'-3153' MIRU PU. Plug and Abandon as follow: Spot 25 SX or 100' whichever is greater "C" @ 3000' Spot 50 SX "C" @ 1600' Spot 10 SX "C" @ Surface		
MIRU PU. Plug and Abandon as follow: Spot 25 SX or 100' whichever is greater "C" @ 3000'		
	Spot 50 SX "C" @ 1600'	
	Spot 10 SX "C" @ Surface	/e = = = = = = = = = = = = = = = = = = =
Remove surface equipment. Install 1	Madaga	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
Remove surface equipment. Instan	THE OIL CONSERVATION	AN DIVISION MUSTO
_	THE OIL CONSERVATION	OC DDIOD TO THE
	BE NOTIFIED 24 HOUR	15 PRIVATO TIL
BEGINNING OF PLUGGING OPERATIONS.		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-		
grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.		
CHONATURE AND A CONTRACT OF A		
SIGNATURE JOST MAL	TITLE AGENT, BY KAY SOWDERS	_DATE05/23/05
Type or print name (HSCOTT DAVIS BY KAY SOWDERS E-mail address CAPATAZI@SBCGLOBAL.NET		
Telephone No.432-620-8820		
For State Use Only		
OG FIELD REPRESENTATIVE II/STAFF MANMAR 3 1 2005		
APPROVED BY: TITLE DATE		
Conditions of Approval (if any).		
	Zut-	