

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
March 4, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-02186
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1576
7. Lease Name or Unit Agreement Name West Vacuum Unit
8. Well Number 17
9. OGRID Number
10. Pool name or Wildcat Vacuum Grayburg San Andres

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other ☐ Injection

2. Name of Operator  
Chevron USA Inc

3. Address of Operator  
15 Smith Rd, Midland, TX 79705

4. Well Location  
Unit Letter H : 1980 feet from the North line and 660 feet from the East line  
Section 33 Township 17-S Range 34-E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL H Sect 33 Twp 17S Rng 34E Pit type Steel Depth to Groundwater 80 Distance from nearest fresh water well Over 1000'  
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ;  
1980 feet from the North line and 660 feet from the East line (Steel Tank)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD 24 hours prior too MI & RU.
2. RIH Tag CIBP at 4000, spot 25sx, plug from 4000-3800 (S. Andres) WOC Tag 3750.
3. Displace hole w/MLF, 9.5# Brine w/12.5# gel P/BBL.
4. Spot 25sx, plug from 2700-2500 (Yates, B-Salt).
5. Spot 25sx plug 1550-1300 (9 5/8 Shoe, T-Salt) WOC Tag 1250.
6. Spot 30sx plug 300-Surf (Surf) WOC Tag Surf.
7. Install dry hole marker 5-19-05.

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Jimmy Bagley TITLE Consultant DATE 5/23/05  
Type or print name Jimmy Bagley E-mail address: Telephone No. 432-561-8600

(This space for State use)

APPROVED BY Gary W. Wink ORIGINAL SIGNED BY GARY W. WINK  
Conditions of approval, if any: FIELD REPRESENTATIVE / STATE MANAGER DATE

JUN 01 2005