Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103	
District I	Energy, Minerals	and Natu	ral Resources	THE LABORATOR	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	0.10.10.10.10.10.10.10.10.10.10.10.10.10			WELL API NO 3	0-025-02292
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			5. Indicate Typ	e of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STATE	✓ FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NIVI 67303 S. St. Francis Dr., Santa Fe, NM			6. State Oil & (Gas Lease No.
87505 SUNDRY NOTION	CES AND REPORTS OF	N WELLS	3	7. Lease Name	or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				West Vacuum Unit	
1. Type of Well:			8. Well Number	r	
Oil Well Gas Well Other				38	
2. Name of Operator Chevron USA Inc				9. OGRID Number	
3. Address of Operator 15 Smith Rd, Midland, TX 79705				Pool name or Wildcat Vacuum Grayburg San Andres	
4. Well Location				Vacuum G	nayburg Gan Andres
	3 30 1 980 feet from the	Seut	th line and	660 feet fi	rom the East line
Section 5	Township 1	8-S R:	ange 34-E	имрм Lea	County
Section	11. Elevation (Show wh				
Pit or Below-grade Tank Application (For	l pit or below-grade tank clos	ures, a form	C-144 must be attache	d)	
Pit Location: UL A Sect 5 Twp 1					nearest fresh water well Over 1000
Distance from nearest surface water	Below-grade Tank Loc				;
1980 feet from the South line and 6	660 feet from the East	_line (S	Steel Tank)		10/981931
12. Check A	Appropriate Box to In	dicate N			
NOTICE OF IN		_		SEQUENT R	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WOR	к 🛚	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AI	ND 🗆	
OTHER:			OTHER:		
13. Describe proposed or comp					
of starting any proposed we or recompletion.	ork). SEE RULE 1103. I	For Multip	ole Completions: At	tach wellbore dia	gram of proposed completion
 Notified OCD 24 hrs prior to MI 8 RIH Tag CIBP at 4284, spot 25s; 		Androe) M	IOC Tea 4080	7. Install Dry H	ole Marker 5-24-05.
3. Displace Hole W/MLF, 9.5# Brind	e W/12.5#gel P/BBL.	•	· ·		
 Perf 4 holes @ 2600 Unable to E (Yates) WOC Tag @ 2394. 	EPIR @ 1500# Spot 25sx Plu	g from 264	6-2393		
5. Perf 4 holes @ 1670 Sqz 150sx					
6. Perf 4 holes @ 300, Sqz 100sx p I hereby certify that the information				e and belief I for	ther certify that any nit or helaw
grade tank has been/will be constructed or	closed according to NMOCD	guidelines	, a general permit	or an (attached) alte	rnative OCD-approved plan .
SIGNATURE /		TITLE	Consulta	nt	DATE 5-24-05
Type or print name Simmy Bag	ley O	E-mail a	ddress:		Telephone No. 432-561-8600
(This space for State use)	1				
91.	1 / ORIGINALS	IGHED	57		
APPPROVED BY Way	I II IO ABY AND VA				HIM a 1 acce
Conditions of approval, if any		MAKE	HATIVE IVSTAFF	MANAGEL	DATE JUN 0 1 2005

Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.