Form 3160-5. (JUNE 1990)

New Mexico Oil Conservation Division, Dist **UNITED STATES** SPAN. French Drive DEPARTMENT OF THE INTE

BUREAU OF LAND MANAGEMENTS, NM 88248

nsoutci l	POKM	APPK	UVED	
			1004-01	35

ludget	Bure	eau	No.	10	04-0135
Exp	ires:	Ма	rch 3	1.	1993

}	L	Expires:	Marc	h 31,	199
	5.	Lease Designation	on and	Seria	iΝ

NM-27805

SUNDRY NOTICES AND	REPORTS ON WELLS
--------------------	------------------

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Lise "APPLICATION FOR PERMIT-" for such proposals

6. If Indian, Allottee or Tribe Name

New Construction

SUBMI	7. If Unit or CA, Agreement Designation	
Type of Well Oil Gas		
X Well Well Other		8. Well Name and No.
2. Name of Operator		Lechuza Federal #5
STRATA PR	ODUCTION COMPANY	9. API Well No.
3. Address and Telephone No. P. O. Box 10	030	30-025-31801
Roswell, Nev	v Mexico 88202-1030 505-622-1127	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Sur	vey Description)	Livingston Ridge Delaware East
1650' FSL 8		11. County or Parish, State
Section 15-22	2S-32E	Lea County, New Mexico
12. CHECK APPROPRIATE BOX	((s) TO INDICATE NATURE OF NOTICE	, REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Nation of Intent	X Abandonment	Change of Plans

Subsequent Report	Plugging Back		Non-Routine Fracturing	
	Casing Repair		Water Shut-Off	
Final Abandonment Notice	Altering Casing		Conversion to Injection	
	OTHER		Dispose Water	
	 •		port results of multiple completion on W	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Strata Production Company requests approval to plug and abandon the well in the following manner:

- Spot 35' of cement on CIBP @ 7000'. 1.
- Plug 4380 4580', 25 sacks, Tag Plug. 2.
- Cut csg and pull 5 1/2" @ 2800'. 25 sacks in csg stub and 25 sacks out of csg stub. 11213 14
 Top of Salt plug @ 900 1200' 35 sacks of cement. TOC @ 2900'. 3.
- Top of Salt plug @ 900 1200' 35 sacks of cement. TOC @ 2900'. 4.
- 510 710' Tag Plug, 35 sacks of cement. 5.
- 6.
- 7. install dry hole marker.
- Remove equipment. 8.
- Clean and rip location per BLM guidelines. 9.

14. I hereby certify that the foregoing is true and correct Signed Signed South	Title Production Records	Date_	05/24/2005
(This space for Federal or State office use) Approved SGD.) DAVID & GLASS	Title STROLELM ENGINEER	Date	JUN 0 6 2005
Conditions of approval, if any:			•

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

