

June 7, 2005

Ms Donna Mull New Mexico Oil Conservation Division 1625 N. French Drive Hobbs, NM 88240

RE: C. E. Lamunyon #7 30-025-10828

Dear Ms Mull:

To confirm our conversation of last week, this well was not directionally drilled. A whipstock was set to exit the casing and make an open hole completion. After exiting the casing, the hole was drilled straight. No directional control was attempted & no directional surveys were run. I have previously given this information to someone else in your office. If you have any questions, please give me a call.

Sincerely,

Rex/A. Masper

Division Operations Supervisor