State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION		
<u>DISTRICT I</u> 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-	07514
DISTRICT II	,		5. Indicate Type of Lease	FFE W
1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410			6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			NORTH HOBBS (G/SA) UNIT	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			Section 31	
Type of Well: Oil Well Gas Well Other Injector			8. Well No. 121	
Name of Operator Occidental Permian Ltd.			9. OGRID No. 157984	
3. Address of Operator			10. Pool name or Wildcat	HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS,	NM 88240 505/39	7-8200		
4. Well Location Unit Letter F: 1980 Feet From The NORTH 990 Feet From The WEST Line				
Unit Letter E : 1980	Feet From The NORTH			
Section 31	Township 18-S 11. Elevation (Show whether DF, RK	Range $38-E$ (B, RT GR, etc.)	NMPM	LEA County
	3653' GR			
Pit or Below-grade Tank Application or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP	NS. PLUG & AE	BANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	Т ЈОВ	
OTHER:		OTHER:	Failed M	IIT X
OTHER: OTHER: Failed MIT X 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion or recompletion or recompletion. RUPU. Ru WIRELINE TRUCK. Set 1.875 "F" plug in profile. Test tbg to 3000 psi. Held OK.				
1. RUPU. Ru WIRELINE TRUCK. 2. Set 1.875 "F" plug in profile. Test tbg to 3000 psi. Held OK.				
1. RUPU. Ru WIRELINE TRUCK. 2. Set 1.875 "F" plug in profile. Test tbg to 3000 psi. Held OK.				
3. Tst csg to 1000 psi for 20 min. Held OK				
4. Test csg to 600 psi for 30 min and chart for the NMOCD.				
5. RDPU. Clean Location.				
3. Tst csg to 1000 psi for 20 min. Held OK 4. Test csg to 600 psi for 30 min and chart for the NMOCD. 5. RDPU. Clean Location. Rig Up Date: 05/25/2005 Rig Down Date: 05/25/2005				
Rig Down Date: 05/25/2005			/5 ² /2	~~~/ ~~/
•			12021223	9181113
			300	Lander 1 and 1
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or				
closed according to NMOCD guidelines	, a general permit	or an (attached) alternative	e OCD-approved	
\mathcal{D} $l+1$		plan		
SIGNATURE X	-ilful	TITLE Workover Com	pletion Specialist DATE	06/01/2005
TYPE OR PRINT NAME Robert Gilb	ert E-mail address:	robert_gilbert@oxy.com	TELEPHONE NO.	505/397-8206
For State Use Only	1. 1. 16		and spirit file.	
APPROVED BY CONDITIONS OF APPROVAL FANY:	1 Diport	HILE	E II/STAFF MANAGERATI	<u> </u>
APPROVED BY AUGULE TITLE CONDITIONS OF APPROVAL FANY: OC FIELD REPRESENTATIVE II/STAFF MANAGERATE OC FIELD REPRESENTATIVE II/STAFF MANAGERATE				

