Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
Office District I	Energy, Minerals and Natural Resources		WELL API NO.
1625 N. French Dr., Hobbs, NM 88240	OH GOMODDIA MION DIVIGION		30-025-37305
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
District III	1625 N. FRENCH DRIVE HOBBS, NM 88240		STATE FEE 🛛
1000 Rio Brazos Rd., Aztec, NM 87410	HODDS, NW 862	240	6. State Oil & Gas Lease No.
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM			
87505			
1	CES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PRO			GRIZZELL
TO A DIFFERENT RESERVOIR. USE SUCH PROPOSALS.)	2 APPLICATION FOR PERMIT (F	ORM C-101) FOR	8. Well Number
1. Type of Well:			o. Well rumber
Oil Well Gas Well Other	er		14
2. Name of Operator			9. OGRID Number
APACHE CORPORATION 3. Address of Operator			873 10. Pool name or Wildcat
3. Address of Operator			EUNICE; SAN ANDRES, SOUTHWEST 24180
6120 S. YALE, STE. 1500 TULSA, OK	74136		PENROSE SKELLY; GRAYBURG 50350
4. Well Location			
	: feet from the		
Section 8 Town		_	J
6.16.4 医克里克尔特别多种的	11. Elevation (Show whether DF 34)		
Pit or Below-grade Tank Application (For	- ·		<u>d)</u> (37.70253037
Pit Location: ULSectTwp			(.00)
Distance from nearest surface water		-	12 (2)
	_		
feet from theline and			2 0 00
12. Check Appropriate Box to Indicate N	ature of Notice, Report or Other Data		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
NOTICE OF INT	_	s	SUBSEQUENT REPORT OF SOME OF
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	
TEMPODADU V ADAMDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS. ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DA	LLING OPNS. ABANDONMENT
PULL OR ALTER CASING	MULTIPLE	CASING TEST AN	
	COMPLETION	CEMENT JOB	
OTHER:		OTHER SPUD	SURF. CSG., TD, LOG, PROD. CSG.
			, 33111 . 333., 13, 233, 1 1135. 333.
			including estimated date of starting any proposed work). Sl
RULE 1103. For Multiple Completions: F	Attach wellbore diagram of proposed comp	letion or recompletion.	
7/2/05 DRILL 12-1/4 HOLE FROM 0' TO 432' -TD @23:00 HRS 7/2/2005 - :CIRC & COND TO RUN CSG - DROP TOTCO & TOH TO RUN 8.625" CSG - RIG UI AND RUN 8.625" CSG -RIG DOWN CSG HEAD & WASH 70' TO BOTTOM -CIRCULATE -CMT 8.625" CSG W/ 375 SKS CLASS C CMT, CIRC 42 SKS,			
AND RUN 8.625" CSG -RIG DO FLOAT HELD -WOC	OWN CSG HEAD & WASH 70' TO BOT	TOM -CIRCULATE -CI	MT 8.625" CSG W/ 375 SKS CLASS C CMT, CIRC 42 SK
) PSI "OK" NIPPLE UP BOP'S & CHOKE MANIFOLD EMENT @ 409' WAIT ON CEMENT DRILL CEMENT.
			ES DRILL 7-7/8" HOLE FROM 973' TO 1130' WLS @
3803' 1 DEG DRLG FROM 3834	4' TO 3898' RIG REPAIR - TOH TO 3743	CHANGE SWIVEL PA	ACKING DRLG FROM 3898' TO 4023' RIG REPAIR - TO
TO 3707' HYDRAULIC SWIVE SWIVEL TIH F/ 3707' TO 4023'	L SHEARED BOLTS IN DRIVE GEAR.	CAPSTAR MECHANIC	CON LOCATION FOR REPAIRS. REPAIR RIG, DRAUL FF/ 4436' TO 4610'. CIRCULATE AND CONDITION HOL
FOR LOGS TOH F/ LOGS & C	SG RIG UP & LOG W/ HALLIBURTON	(LOGGERS TD 4515').	COMPLETE LOGGING OPERATIONS, TURN OVER TO
COMPLETION. INSTALL 5-1/2	"CASING RAMS -R/U AND RUN 103 J	OINTS OF 5-1/2" CASI	NG. WASH FROM 4515' TO 4610'. PREPARE TO CEMEI LD. CIRC 45 SKS ND/BOP, SET SLIPS & CUT OFF,
CW11 3-1/2 17# 355 W/000 3K3	LEAD, 430 SKS TAIL. BUMF FLUG WI	VO.UU IIKS. FLUAT IIE.	LD. CIRC 43 SAS ND/BOP, SET SLIPS & CUT OFF,
RELEASE RIG @ 10:00 HRS	7/10/2005.		
I hereby certify that the information above is tr	ue and complete to the best of my knowled	ge and belief. I further	certify that any pit or below-grade tank has been/will be
constructed or closed according to NMOCD	guidelines 🔲, a general permit 🔲 or ar	(attached) alternative	OCD-approved plan □.
SIGNATURE and William	TITLE SR. DEPT. CLEF	rkdate_7/	120/05
Type or print name LANA WILLIAMS	E-mail address: lana.williams@a	pachecorp.com	Telephone No. 918-491-4980
(This space for State use)		P	
	PETROL FUM ENG		2005
APPPROVED BY Conditions of approval any:	TITLE	DATE	