Subtitit 3 Copies To Appropriate District State of New Mexico	Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources	May 27, 2004
District 11 OUL CONSERVATION DIVISION	30-025-20427
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	V-7274
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Snapper State
PROPOSALS.) 1. Type of Well: Oil Well 🔀 Gas Well 🗌 Other	8. Well Number 5
2. Name of Operator	9. OGRID Number
Mack Energy Corporation	013837
3. Address of Operator P. O. Box 960 Artesia NM 88211 0960	I 0. Pool name or Wildcat Wildcat Grayburg
P. O. Box 960 Artesia, NM 88211-0960 4. Well Location	
Unit Letter P 660 feet from the South line and	660feet from theEastline
Section <u>14</u> Township <u>16S</u> Range <u>33E</u>	NMPM County Lea
I 1. Elevation (Show whether DR, RKB, RT, GR, etc.,	
Pit or Below-grade Tank Application or Closure	
Pit typeDepth GroundwaterDistance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volume bb1s; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
an an tha 2 and the second	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS P AND A	
	T JOBNE MALE BERNER
OTHER: OTHER:	<b></b>
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
07/18/2005 MIRU drill surface out tag cement @ 280', drill out plug at casing shoe, drill to 700'.	
07/19/2005 RIH tag @ 655' drill to 710', mix mud and circ, pull back into casing. SDFD.	
07/20/2005 RIH tag @ 680' had to drill w/8-10 points, mix mud pill and drill to 700' pull back into casing SDFD. 07/21/2005 RIH tag @ 610' drill w/3 points to 680', 10 points to 700' hole full of redbed. Call Gary Wink w/OCD to get verbal to	
P & A. RIH w/11 joints to 370'(50' below casing shoe) spot 110 sx Class C and circ to surface. Install dry hole marker.	
	A6678 3022
Approved as to plugging of the Well Bore.	
Liability under bond is retained until	A BARA
surface restoration is completed.	S S S S S
I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit	and belief. I further certify that any pit or below- ]or an (attached) alternative OCD-approved plan 🗌
SIGNATURE ( Jeny W Shevell TITLE Production Clerk	DATE 7/26/2005
Type or print name Jerry W. Sherrell E-mail address: jerrys@macke	nergycorp.comTelephone No. (505)748-1288
For State Use Only	
APPROVED BY:	DATEAUG 0 1 2005
Conditions of Approval (if any)	