_ Office_	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-09641
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	Suitu 1 0, 1 111 0 / 3 0 5	NM 12612
	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	NM 70962X
1. Type of Well: Oil Well	Gas Well Other X Injector	8. Well Number Cooper Jal Unit 135 w
2. Name of Operator	Ous wen Other A mjector	9. OGRID Number 193003
2. Name of operator	SDG Resources L. P.	9. OGRID Nulliber 193003
3. Address of Operator	P. O. Box 1390	10. Pool name or Wildcat JALMAT:
P	Montrose, CO 81401	Tansill, Yates & 7-Rivers; LANGLIE
	,	MATTIX: 7-Rivers, Queen
4. Well Location		
Unit Letter O :	990feet from theSOUTH line and	
Section 24	Township 24S Range 36E	
THE STATE OF THE S	11. Elevation (Show whether DR, RKB, RT, GR, etc. 3,318' KB	z.)
Pit or Below-grade Tank Application 🔀	or Closure	Marie Control of the
Pit type_DIRTDepth to Groundwater_	_130 feetDistance from nearest fresh water well_>1000 feet_	Distance from nearest surface water >1000 feet
Pit Liner Thickness: 12 mil		ion Material Synthetic
12. Check A	Appropriate Box to Indicate Nature of Notice	, Report or Other Data
NOTICE OF IN	ITENTION TO:	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON ☐ REMEDIAL WO	
TEMPORARILY ABANDON		RILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL , CASING/CEMEN	—
	Pit Permit	
OTHER: Clean out injector with bit	to 3,650' and Acidize. OTHER:	
Describe proposed or comp	pleted operations. (Clearly state all pertinent details, a	nd give pertinent dates, including estimated date
of starting any proposed wo	ork). SEE RULE 1103. For Multiple Completions: A	attach wellbore diagram of proposed completion
or recompletion.		
Objectives Clean out Jalmet/La		
Objective: Clean out Jaimat/La	1. Marie de la companya de la compa	// S
	nglie Mattix injector w/bit to 3,650' and Acidize with	4,000 gallons 15% NEFE HCl acid.
	nglie Mattix injector w/bit to 3,650' and Acidize with	4,000 gallons 15% NEFE HCI acid.
1. MIRU Pulling Unit.	·	4,000 gallons 15% NEFE HCl acid.
 MIRU Pulling Unit. POOH with 2 3/8" IPC tubing a 	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer.	The state of the s
 MIRU Pulling Unit. POOH with 2 3/8" IPC tubing at RIH with 4 3/4" bit & 6 - 3 ½" of the second second	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow	The state of the s
 MIRU Pulling Unit. POOH with 2 3/8" IPC tubing at 3. RIH with 4 3/4" bit & 6 - 3 1/2" of 4. RIH with 5 1/2" packer and set at 3. 	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'.	The state of the s
 MIRU Pulling Unit. POOH with 2 3/8" IPC tubing a RIH with 4 3/4" bit & 6 - 3 1/2" o RIH with 5 1/2" packer and set a Acidize open hole 2,925'-3,650 POOH with 2 7/8" work string 	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'. O' with 3,000 gallons 15% NEFE HCl acid. and lay down packer.	n bit and drill collars.
 MIRU Pulling Unit. POOH with 2 3/8" IPC tubing a RIH with 4 3/4" bit & 6 - 3 ½" o RIH with 5 ½" packer and set a Acidize open hole 2,925'-3,650 POOH with 2 7/8" work string RIH with 5 ½" x 2 3/8" Baker I 	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'. O' with 3,000 gallons 15% NEFE HCl acid. and lay down packer. Model AD-1 Tension packer to 2,925'; circulate annul	n bit and drill collars.
 MIRU Pulling Unit. POOH with 2 3/8" IPC tubing a RIH with 4 3/4" bit & 6 - 3 1/2" of RIH with 5 1/2" packer and set a Acidize open hole 2,925'-3,650 POOH with 2 7/8" work string RIH with 5 1/2" x 2 3/8" Baker 1 Set packer and test annulus to 5 	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'. "With 3,000 gallons 15% NEFE HCl acid. and lay down packer. Model AD-1 Tension packer to 2,925'; circulate annul 500 psig for 30 minutes. Pull chart for NMOCD. Place	n bit and drill collars.
 MIRU Pulling Unit. POOH with 2 3/8" IPC tubing a RIH with 4 3/4" bit & 6 - 3 1/2" of RIH with 5 1/2" packer and set a Acidize open hole 2,925'-3,650 POOH with 2 7/8" work string RIH with 5 1/2" x 2 3/8" Baker 1 Set packer and test annulus to 5 Maximum permitted injection p 	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'. "With 3,000 gallons 15% NEFE HCl acid. and lay down packer. Model AD-1 Tension packer to 2,925'; circulate annul 500 psig for 30 minutes. Pull chart for NMOCD. Place pressure is 600 psig.	lus with inhibited packer fluid. well on injection at approximately 270 bwpd.
 MIRU Pulling Unit. POOH with 2 3/8" IPC tubing a RIH with 4 3/4" bit & 6 - 3 1/2" of RIH with 5 1/2" packer and set a Acidize open hole 2,925'-3,650 POOH with 2 7/8" work string RIH with 5 1/2" x 2 3/8" Baker 1 Set packer and test annulus to 5 Maximum permitted injection p 	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'. "With 3,000 gallons 15% NEFE HCl acid. and lay down packer. Model AD-1 Tension packer to 2,925'; circulate annul 500 psig for 30 minutes. Pull chart for NMOCD. Place	lus with inhibited packer fluid. well on injection at approximately 270 bwpd.
 MIRU Pulling Unit. POOH with 2 3/8" IPC tubing a RIH with 4 3/4" bit & 6 - 3 1/2" of RIH with 5 1/2" packer and set a Acidize open hole 2,925'-3,650 POOH with 2 7/8" work string RIH with 5 1/2" x 2 3/8" Baker 1 Set packer and test annulus to 5 Maximum permitted injection p 	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'. "With 3,000 gallons 15% NEFE HCl acid. and lay down packer. Model AD-1 Tension packer to 2,925'; circulate annul 500 psig for 30 minutes. Pull chart for NMOCD. Place pressure is 600 psig.	n bit and drill collars. Jus with inhibited packer fluid. well on injection at approximately 270 bwpd. 4 with NMOCD.
 MIRU Pulling Unit. POOH with 2 3/8" IPC tubing a RIH with 4 3/4" bit & 6 - 3 1/2" o RIH with 5 1/2" packer and set a Acidize open hole 2,925'-3,650 POOH with 2 7/8" work string RIH with 5 1/2" x 2 3/8" Baker I Set packer and test annulus to 5 Maximum permitted injection p Fold Pit Liner inward, cover with 	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'. O' with 3,000 gallons 15% NEFE HCl acid. and lay down packer. Model AD-1 Tension packer to 2,925'; circulate annul 500 psig for 30 minutes. Pull chart for NMOCD. Place pressure is 600 psig. oth 20 mil liner and cover with top soil. File Form C14	lus with inhibited packer fluid. well on injection at approximately 270 bwpd. 4 with NMOCD.
 MIRU Pulling Unit. POOH with 2 3/8" IPC tubing a RIH with 4 ¾" bit & 6 - 3 ½" o RIH with 5 ½" packer and set a Acidize open hole 2,925'-3,650 POOH with 2 7/8" work string RIH with 5 ½" x 2 3/8" Baker I Set packer and test annulus to 5 Maximum permitted injection p Fold Pit Liner inward, cover with 	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'. O' with 3,000 gallons 15% NEFE HCl acid. and lay down packer. Model AD-1 Tension packer to 2,925'; circulate annul 500 psig for 30 minutes. Pull chart for NMOCD. Place pressure is 600 psig. ith 20 mil liner and cover with top soil. File Form C14	It with inhibited packer fluid. Well on injection at approximately 270 bwpd. 4 with NMOCD. WEY-657 ge and belief. I further certify that any pit or below.
 MIRU Pulling Unit. POOH with 2 3/8" IPC tubing a RIH with 4 ¾" bit & 6 - 3 ½" o RIH with 5 ½" packer and set a Acidize open hole 2,925'-3,650 POOH with 2 7/8" work string RIH with 5 ½" x 2 3/8" Baker I Set packer and test annulus to 5 Maximum permitted injection p Fold Pit Liner inward, cover with 	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'. "With 3,000 gallons 15% NEFE HCl acid. and lay down packer. Model AD-1 Tension packer to 2,925'; circulate annul 500 psig for 30 minutes. Pull chart for NMOCD. Place pressure is 600 psig.	It with inhibited packer fluid. Well on injection at approximately 270 bwpd. 4 with NMOCD. WEY-657 ge and belief. I further certify that any pit or below.
1. MIRU Pulling Unit. 2. POOH with 2 3/8" IPC tubing a 3. RIH with 4 3/4" bit & 6 - 3 1/2" of 4. RIH with 5 1/2" packer and set a 5. Acidize open hole 2,925'-3,650 6. POOH with 2 7/8" work string 7. RIH with 5 1/2" x 2 3/8" Baker 18. Set packer and test annulus to 5 9. Maximum permitted injection p 10. Fold Pit Liner inward, cover with the set of 10. In the set of 10. I	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'. "o' with 3,000 gallons 15% NEFE HCl acid. and lay down packer. Model AD-1 Tension packer to 2,925'; circulate annul 500 psig for 30 minutes. Pull chart for NMOCD. Place pressure is 600 psig. ith 20 mil liner and cover with top soil. File Form C14 above is true and complete to the best of my knowledge closed according to NMOCD guidelines , a general permit.	In bit and drill collars. Substitute the substitute of the substi
 MIRU Pulling Unit. POOH with 2 3/8" IPC tubing a RIH with 4 ¾" bit & 6 - 3 ½" o RIH with 5 ½" packer and set a Acidize open hole 2,925'-3,650 POOH with 2 7/8" work string RIH with 5 ½" x 2 3/8" Baker I Set packer and test annulus to 5 Maximum permitted injection p Fold Pit Liner inward, cover with 	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'. O' with 3,000 gallons 15% NEFE HCl acid. and lay down packer. Model AD-1 Tension packer to 2,925'; circulate annul 500 psig for 30 minutes. Pull chart for NMOCD. Place pressure is 600 psig. ith 20 mil liner and cover with top soil. File Form C14	n bit and drill collars. lus with inhibited packer fluid. well on injection at approximately 270 bwpd. 4 with NMOCD. ge and belief. I further certify that any pit or beloward or an (attached) alternative OCD-approved plan .
1. MIRU Pulling Unit. 2. POOH with 2 3/8" IPC tubing a 3. RIH with 4 3/4" bit & 6 - 3 1/2" o 4. RIH with 5 1/2" packer and set a 5. Acidize open hole 2,925'-3,650 6. POOH with 2 7/8" work string 7. RIH with 5 1/2" x 2 3/8" Baker 1 8. Set packer and test annulus to 5 9. Maximum permitted injection p 10. Fold Pit Liner inward, cover with the constructed or SIGNATURE	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'. O' with 3,000 gallons 15% NEFE HCl acid. and lay down packer. Model AD-1 Tension packer to 2,925'; circulate annul 500 psig for 30 minutes. Pull chart for NMOCD. Place pressure is 600 psig. ath 20 mil liner and cover with top soil. File Form C14 above is true and complete to the best of my knowledge closed according to NMOCD guidelines , a general permit.	In bit and drill collars. Solution with inhibited packer fluid. Well on injection at approximately 270 bwpd. 4 with NMOCD. Solution are approximately 270 bwpd. 4 with NMOCD. Solution and belief. I further certify that any pit or belowater an (attached) alternative OCD-approved plan . Engineer DATE_7/28/05_
1. MIRU Pulling Unit. 2. POOH with 2 3/8" IPC tubing a 3. RIH with 4 3/4" bit & 6 - 3 1/2" o 4. RIH with 5 1/2" packer and set a 5. Acidize open hole 2,925'-3,650 6. POOH with 2 7/8" work string 7. RIH with 5 1/2" x 2 3/8" Baker 1 8. Set packer and test annulus to 5 9. Maximum permitted injection p 10. Fold Pit Liner inward, cover with the constructed or SIGNATURE Type or print name	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'. O' with 3,000 gallons 15% NEFE HCl acid. and lay down packer. Model AD-1 Tension packer to 2,925'; circulate annul 500 psig for 30 minutes. Pull chart for NMOCD. Place pressure is 600 psig. ath 20 mil liner and cover with top soil. File Form C14 above is true and complete to the best of my knowledge closed according to NMOCD guidelines , a general permit.	In bit and drill collars. Substitute the substitute of the substi
1. MIRU Pulling Unit. 2. POOH with 2 3/8" IPC tubing a 3. RIH with 4 3/4" bit & 6 - 3 1/2" o 4. RIH with 5 1/2" packer and set a 5. Acidize open hole 2,925'-3,650 6. POOH with 2 7/8" work string 7. RIH with 5 1/2" x 2 3/8" Baker 1 8. Set packer and test annulus to 5 9. Maximum permitted injection p 10. Fold Pit Liner inward, cover with the constructed or SIGNATURE	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'. O' with 3,000 gallons 15% NEFE HCl acid. and lay down packer. Model AD-1 Tension packer to 2,925'; circulate annul 500 psig for 30 minutes. Pull chart for NMOCD. Place pressure is 600 psig. ith 20 mil liner and cover with top soil. File Form C14 above is true and complete to the best of my knowledger closed according to NMOCD guidelines , a general permit of TITLE_Senior Petroleum I E-mail address: Domingo@sdgreso	In bit and drill collars. It with inhibited packer fluid. Well on injection at approximately 270 bwpd. 4 with NMOCD. It with very season of the season o
1. MIRU Pulling Unit. 2. POOH with 2 3/8" IPC tubing a 3. RIH with 4 3/4" bit & 6 - 3 1/2" of 4. RIH with 5 1/2" packer and set a 5. Acidize open hole 2,925'-3,650 of POOH with 2 7/8" work string 7. RIH with 5 1/2" x 2 3/8" Baker 1 8. Set packer and test annulus to 5 9. Maximum permitted injection proceeding 10. Fold Pit Liner inward, cover with the set of the	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'. O' with 3,000 gallons 15% NEFE HCl acid. and lay down packer. Model AD-1 Tension packer to 2,925'; circulate annul 500 psig for 30 minutes. Pull chart for NMOCD. Place pressure is 600 psig. ith 20 mil liner and cover with top soil. File Form C14 above is true and complete to the best of my knowledger closed according to NMOCD guidelines , a general permit of TITLE_Senior Petroleum I E-mail address: Domingo@sdgreso	In bit and drill collars. It with inhibited packer fluid. Well on injection at approximately 270 bwpd. 4 with NMOCD. It with very season of the season o
1. MIRU Pulling Unit. 2. POOH with 2 3/8" IPC tubing a 3. RIH with 4 3/4" bit & 6 - 3 1/2" o 4. RIH with 5 1/2" packer and set a 5. Acidize open hole 2,925'-3,650 6. POOH with 2 7/8" work string 7. RIH with 5 1/2" x 2 3/8" Baker I 8. Set packer and test annulus to 5 9. Maximum permitted injection p 10. Fold Pit Liner inward, cover with I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name For State Use Only	and 5 ½" x 2 3/8" Baker Model AD-1 tension packer. drill collars on 2 7/8" work string. POOH and lay dow at 2,925'. O' with 3,000 gallons 15% NEFE HCl acid. and lay down packer. Model AD-1 Tension packer to 2,925'; circulate annul 500 psig for 30 minutes. Pull chart for NMOCD. Place pressure is 600 psig. ith 20 mil liner and cover with top soil. File Form C14 above is true and complete to the best of my knowledger closed according to NMOCD guidelines , a general permit of TITLE_Senior Petroleum I E-mail address: Domingo@sdgreso	aus with inhibited packer fluid. Well on injection at approximately 270 bwpd. 4 with NMOCD. Ge and belief. I further certify that any pit or belowdor an (attached) alternative OCD-approved plan . Engineer

CURRENT COM	ADI ETION SCHEMATIC	LEAGE NA	······	Cooper lel Unit		T	405 14/114	
CURRENT COMPLETION SCHEMATIC		STATUS:	ME Active	Cooper Jal Unit Water Inject		WELL NO.	135 WIW	
1888	*****	LOCATION		1980 FEL, Sec 24, T - 24S, R - 36E		API# 30-025-	09641	
		SPUD DAT	E:	TD 3650	KB 3,318'	DF		
		INT. COMP.	DATE: 03/01/54		GL 3,312'			
urface Csg = Size: 11 in Size: 8 5/8 in Set @: 290 ft s Cmt: 125 Circ: Yes DC @: surf DC by: circ		ELECTRIC LOGS: Micro Laterolog (2-23-54 Schlumberger) GR-CNL (8-25-86 Dresser Atlas) GR-VDR-CBL (8-25-86 Dresser Atlas) HYROCARBON BEARING ZONE DEPTH TOPS:						
		SURF.	8.5/8" - 28# L55 cot@ 1	CASING				
		PROD.	5 1/2" - 14#, J-55 set@ 2	290' Cmt'd w/125 sxs - circ cmt to s 3472' Cmt'd w/400 sxs - TOC @ 2	iurt. '728' from surf by cem	ent hand loc		
		LINER	None			ent bond log.		
		CSG. PERFS: OPEN HOLE: 3472 - 3650' Perfs: 3019', 22, 24, 26, 28, 30, 32, 34, 43, 45, 459, 62, 70, 72, 74, 76, 82, 93, 97, 3102', 06, 09, 16, 27, 30, 38, 45, 51, 56, 65, 70, 76, 83, 90, 94, 3201', w/ 2 spf (84 holes total 3285' - 3302' & 3358 - 62' w/ 1 spf (21 holes total)						
TOC@ 2721 By CBL	TUBING DE	ETAIL 4/5/1999		ROD DETAIL				
	TOC@ 2728	·		.				
	By CBL		Length (ft)	<u>Detail</u>				
			6.00 KB					
				8" 4.7#, CL, J-55, 8rd EUE tbg.				
			3.00 1- 5 1/2" x 2 2925.00 btm	2 3/8" Baker Model AD-1 packer				
			2925.00 btm					
		WELL HISTORY SUMMARY						
		1-Mar-54		72 - 3575' (7 RVRS/Queen OH). Natural	completion.			
		9-Sep-54	IP= 51 bopd, 0 bwpd, & 72 Mcfgpd (flowing) 9-Sep-54 Frac w/ 4,000 gals ise oii & 4,000#/s sand.					
	15-Jun-73 Placed well on rod pump.							
	8-Oct-74							
			11-Feb-75 Tagged for fill - No fill.					
		25-Aug-00	29-Aug-86 C/O OH 3480 - 3575' (95' fill). Deepened to 3650'. Ran CBL, TOC @ 2728'. Acdz'd OH (3472 - 3650') w/z,000 gals; Frac w/34,000 gals X-L gel carring 80,000#'s 12/20 sand in 2 equal stages. Max sand concetration of 7 ppg. C/O to 3650'.					
		30-Sep-86						
pkr @ 2925'		i	perfs w/ 2.000 gals; Frac w/ 30,000 gals X-L gel carring 50,000#'s 12/20 sand in 2 equal stages using rock salt diversion. Max sand					
		İ	concentration 7 ppg. C/O to 3650'. Lost RBP in OH. Top @ 3530'. CONVERTED TO COMINGLED DOWNHOLE INJECTOR. (Jalmat & Langlie Mattix)					
		13-Feb-87	C/O OH fill from 3472 - 3524		& Langlie Mattix)			
		9-Sep-87	C/O OH fill from 3495 - 3524	l' (29' fill). PBTD @ 3524'.				
	3019 - 3097	22-Jul-88	C/O OH fill from 3475 - 3524					
		15-Nov-93 9-Jan-94	Replaced 2 jts tbg & rod pm Ran 91 jts - 2 3/8" tbg & pkr.	p. Placed well on production.				
300 300		5-Dec-94		to 3524' (scale & formation) Tagged so	lid @ 3524'. Acdz'd perf	s & OH w, 8,400 dats 20%	6 NEFE HCL	
9335 933	3102 - 3194	j	mixed with 170 gals xylene u	sing 5,600#'s rock salt generating 8 stage	es. AIR=3 bpm PM=500	- 126 psi. ISIP = 280 psi,		
		2 00-00	P5min = vacuum. Ran 2 3/	B"CL.tbg &.pkr. Set pkr @ 2956'. Injec	t @ 933 bwpd, TP=vacu	um.		
983 983 983	3201, 03, &	2-Apr-99 10' 14-Feb-02		& pkr @ 500 psi. OK. Initiate injection x 5' sinker bar). Tag fill @ 3524' (137' o		51.		
3333 3333		1	5 := mm.g oc om (; 1)4)			
Daniel and an O	3285 - 3302							
Production Csg. Size: 7 7/8 in	3358 -3362'							
Size: 5 1/2 in	3300 -3362							
Set@: 3472 ft								
s Cmt: 400					•			
Circ: No DC @: 2728 f/surf								
OC by: CBL	OH Interval							
	3472 - 3650'							
	**************************************	-						
PBTD: 3530 ft	Fill at 3524' CIBP pushed in	to						
TD: 3650 ft	OH to 3530'	.~						
	H ID: 4 3/4 in							