

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 5-27-2004

FILE IN TRIPLICATE

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

1301 W. Grand Ave, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd, Aztec, NM 87410

WELL API NO.

30-025-07493

5. Indicate Type of Lease

STATE ☒ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)

7. Lease Name or Unit Agreement Name

NORTH HOBBS (G/SA) UNIT
Section 31

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

8. Well No. 421

2. Name of Operator

Occidental Permian Ltd.

9. OGRID No. 157984

3. Address of Operator

1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200

10. Pool name or Wildcat HOBBS (G/SA)

4. Well Location

Unit Letter H : 1370 Feet From The NORTH 330 Feet From The EAST Line
Section 31 Township 18-S Range 38-E NMPM LEA County

11. Elevation (Show whether DF, RKB, RT GR, etc.)

3642' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit Type _____ Depth of Ground Water _____ Distance from nearest fresh water well _____ Distance from nearest surface water

Pit Liner Thickness _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

REMEDIAL WORK ☒ ALTERING CASING ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐

PULL OR ALTER CASING ☐ Multiple Completion ☐

CASING TEST AND CEMENT JOB ☐

OTHER: _____

OTHER: _____

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RUPU. Pull and lay down production equipment.
2. Drill out CIBP's @4080' and 4090'.
3. Stimulate perfs 4174-81 and open hole 4190-4260 w/2000 g 15% NEFE HCL acid.
4. Run Beam production equipment. 127 jts 2-7/8" tbg. SN = 4047'.
5. Run 2.5" x 1.50" x 20' pump.
6. RDPU. Clean Location.

Rig Up Date: 07/20/2005

Rig Down Date: 07/22/2005

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE

Robert Gilbert

TITLE Workover Completion Specialist DATE 07/31/2005

TYPE OR PRINT NAME Robert Gilbert

E-mail address: robert_gilbert@oxy.com

TELEPHONE NO. 505/397-8206

For State Use Only

APPROVED BY

Gayle W. Wink

TITLE

DATE

CONDITIONS OF APPROVAL IF ANY:

OC FIELD REPRESENTATIVE II/STAFF MANAGER AUG 10 2005