Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-025-00516
1301 W. Grand Ave., Artesia, NM 88210			5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE x FEE
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			B2229
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			
PROPOSALS.)		MALMAR UNIT	
1. Type of Well:			
Oil Well X Gas Well Other			
2. Name of Operator Mar Oil and Gas Corp.		8. Well No. 316	
3. Address of Operator			9. Pool name
P.O. Box 5155 Santa Fe NM 87502		7. Tool name	
4. Well Location			
Unit Letter P 660 FSL 660 FEL			
Santiar 12	T 1: 150	D 205	VII. (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
Section 12	Township 17S 10. Elevation (Show whether	Range 32E	NMPM County LEA
10. Elevation (Show whether DR, RKB, RT, GR, etc.) GL			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	
TEMPODADU V ADANDON	01141105 51 4110		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	LLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE	CASING TEST AI	
	COMPLETION	CEMENT JOB	
OTHER:	X	OTHER:	x
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of			
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or			
recompilation.			
The well is presently a chart WIW Considered Con Andrea Days 4120 4422			
The well is presently a shut WIW Grayburg, San Andres Perfs 4129-4433 MAR proposes to set a temporary RBP @ 3800' perforate Queen 3500—3540			
Acidize and Frac Queen and test Queen for potential production			
If Queen is not productive then cmt queeze Queen perfs and initiate well back to WIW			
If Queen is productive then temporary abandon Graybury, San Andres perfs according to OCD rules and regulations			
And produce Queen according to OCD rules and regulations			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE de Car		_TITLE : VP Operation	DATE August 10, 2005
SIGNATURE		_IIILE. VF Operation	DATE :August 10, 2005
Type or print name Duane C Winkle	r		Telephone No.505-989-1977
(This space for State use)			
APPPROVED BY TITLETROLEUM ENGINEER DAAUG 1 0 2005			
APPPROVED BY Conditions of approval, if any:	TITPE	INULEUM LINGHALL	DAA146 1 0 2005
11			