

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 5-27-2004

FILE IN TRIPLICATE

OIL CONSERVATION DIVISION

DISTRICT I

1625 N. French Dr. , Hobbs, NM 88240

DISTRICT II

1301 W. Grand Ave, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd, Aztec, NM 87410

1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-05493

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
NORTH HOBBS (G/SA) UNIT
Section 25

8. Well No. 744

9. OGRID No. 157984

10. Pool name or Wildcat HOBBS (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other TA'd ☐

2. Name of Operator
Occidental Permian Ltd.

3. Address of Operator
1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200

4. Well Location
Unit Letter P : 330 Feet From The SOUTH 330 Feet From The EAST Line
Section 25 Township 18-S Range 37-E NMPM LEA County

11. Elevation (Show whether DF, RKB, RT GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐
Pit Type _____ Depth of Ground Water _____ Distance from nearest fresh water well _____ Distance from nearest surface water
Pit Liner Thickness _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ Multiple Completion ☐
OTHER: ☐
SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Return to production ☒

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

*** Well bore was purchased from Rice Engr.

1. RUPU. Drill out CIBP @4170'. Clean out to PBTD @4407'.
2. Set CIBP @4406'.
3. Perforate the following intervals; 4268-75, 4280-83, 4297-4300, 4332-35, 4247-49, 4252-57, and 4360-75 using 2 spf, 120 deg sp ph. (63 holes).
4. Stimulate perms 4268 to 4375 w/1850 g 15% NEFE HCL acid in 22 settings.
5. RIH Reda ESP equipment on 133 jts 2-7/8" tbg w/drain valve. Intake set @4192'.
6. Install QCI wellhead connection.
7. RDPU. Clean Location.

Rig Up Date: 06/21/2005

Rig Down Date: 06/24/2005

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or

closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Robert Gilbert TITLE Workover Completion Specialist DATE 07/14/2005

TYPE OR PRINT NAME Robert Gilbert E-mail address: robert_gilbert@oxy.com TELEPHONE NO. 505/397-8206

For State Use Only

APPROVED BY [Signature] TITLE PAUL F. KAUTZ DATE AUG 25 2005

CONDITIONS OF APPROVAL IF ANY:

ORIGINAL SIGNED BY
PAUL F. KAUTZ
PETROLEUM ENGINEER