Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-28585
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		B-1520-1
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		North Vacuum ABO Unit
	Gas Well Other	8. Well Number 239
2. Name of Operator XTO Energy Inc.		9. OGRID Number 005380
3. Address of Operator 200 N. Lo		10. Pool name or Wildcat
	TX 79701	Vacuum; ABO, North
4. Well Location	1002 foot from the North line and	910 foot from the West line
Unit Letter_E_ :_ Section 25		810feet from the _Westline 84E NMPM County Lea
	11. Elevation (Show whether DR, RKB, RT, GR,	
KB 4015 Pit or Below-grade Tank Application or Closure		
	terDistance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mil		Construction Material
12. Check A	ppropriate Box to Indicate Nature of Noti	ce, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
		DRILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEM	ENT JOB
OTHER: OTHER:		
13. Describe proposed or compl	eted operations. (Clearly state all pertinent details	
13. Describe proposed or compl of starting any proposed wo or recompletion.	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions:	
13. Describe proposed or complete of starting any proposed wo or recompletion.1. MIRU PU, ND WH, NU BO	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions:	
 Describe proposed or complete of starting any proposed wo or recompletion. MIRU PU, ND WH, NU BO PUH & set packer @ 8465' 	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions:	
 Describe proposed or complete of starting any proposed wo or recompletion. MIRU PU, ND WH, NU BOOM OF SET OF	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456)	
 Describe proposed or complete of starting any proposed wo or recompletion. MIRU PU, ND WH, NU BOOM OF STANDARD S	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456)	
13. Describe proposed or complor of starting any proposed wo or recompletion. 1. MIRU PU, ND WH, NU BC 2. PUH & set packer @ 8465' 3. Pmp 2000 gal of 15% HCL 4. Monitor backside for comm A. If communication 1. PUH 2. Set packer	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456) ation @8300'	Attach wellbore diagram of proposed completion
13. Describe proposed or comploof starting any proposed wo or recompletion. 1. MIRU PU, ND WH, NU BC 2. PUH & set packer @ 8465' 3. Pmp 2000 gal of 15% HCL 4. Monitor backside for comm A. If communica 1. PUH 2. Set packer 3. Acdz entir	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456) ation @8300' e ABO interval w/3000 gals 15% HCL (7000 psi r	Attach wellbore diagram of proposed completion
13. Describe proposed or complor of starting any proposed wo or recompletion. 1. MIRU PU, ND WH, NU BC 2. PUH & set packer @ 8465' 3. Pmp 2000 gal of 15% HCL 4. Monitor backside for comm A. If communication 1. PUH 2. Set packer	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456) ation @8300' e ABO interval w/3000 gals 15% HCL (7000 psi rication	Attach wellbore diagram of proposed completion
13. Describe proposed or comploof starting any proposed wo or recompletion. 1. MIRU PU, ND WH, NU BC 2. PUH & set packer @ 8465' 3. Pmp 2000 gal of 15% HCL 4. Monitor backside for comm A. If communica 1. PUH 2. Set packer 3. Acdz entir B. If no commun 1. PUH to 84 2. Set RBP @	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456) ation @8300' ee ABO interval w/3000 gals 15% HCL (7000 psi rication 665' @8465'	Attach wellbore diagram of proposed completion
13. Describe proposed or comploof starting any proposed wo or recompletion. 1. MIRU PU, ND WH, NU BC 2. PUH & set packer @ 8465' 3. Pmp 2000 gal of 15% HCL 4. Monitor backside for comm A. If communica 1. PUH 2. Set packer 3. Acdz entir B. If no commun 1. PUH to 84 2. Set RBP @ 3. Acdz uppe	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456) ation @8300' te ABO interval w/3000 gals 15% HCL (7000 psi recation left) 65' 08465' er ABO perfs (8364 – 8456) w/3000 gals 15% HCI	Attach wellbore diagram of proposed completion nax surface pressure)
13. Describe proposed or complete of starting any proposed wo or recompletion. 1. MIRU PU, ND WH, NU BC 2. PUH & set packer @ 8465' 3. Pmp 2000 gal of 15% HCL 4. Monitor backside for comm A. If communica 1. PUH 2. Set packer 3. Acdz entir B. If no commun 1. PUH to 84 2. Set RBP @ 3. Acdz uppe C. Release RBP & 5. Swab	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456) ation @8300' e ABO interval w/3000 gals 15% HCL (7000 psi rication 165' 08465' ET ABO perfs (8364 – 8456) w/3000 gals 15% HCI & TIH & set RBP @8600', PUH & set packer @85	Attach wellbore diagram of proposed completion nax surface pressure) @ 5 bpm 00'
13. Describe proposed or complete of starting any proposed wo or recompletion. 1. MIRU PU, ND WH, NU BC 2. PUH & set packer @ 8465' 3. Pmp 2000 gal of 15% HCL 4. Monitor backside for comm A. If communica 1. PUH 2. Set packer 3. Acdz entir B. If no commun 1. PUH to 84 2. Set RBP @ 3. Acdz uppe C. Release RBP & 5. Swab 6. Acdz w/27,500 gals WF120,	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456) ation @8300' te ABO interval w/3000 gals 15% HCL (7000 psi recation left) 65' 08465' er ABO perfs (8364 – 8456) w/3000 gals 15% HCI	Attach wellbore diagram of proposed completion nax surface pressure) @ 5 bpm 00'
13. Describe proposed or complete of starting any proposed wo or recompletion. 1. MIRU PU, ND WH, NU BC 2. PUH & set packer @ 8465' 3. Pmp 2000 gal of 15% HCL 4. Monitor backside for comm A. If communica 1. PUH 2. Set packer 3. Acdz entir B. If no commun 1. PUH to 84 2. Set RBP @ 3. Acdz uppe C. Release RBP & 5. Swab	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456) ation @8300' e ABO interval w/3000 gals 15% HCL (7000 psi rication 165' 08465' ET ABO perfs (8364 – 8456) w/3000 gals 15% HCI & TIH & set RBP @8600', PUH & set packer @85	Attach wellbore diagram of proposed completion nax surface pressure) @ 5 bpm 00'
13. Describe proposed or complor of starting any proposed wo or recompletion. 1. MIRU PU, ND WH, NU BC 2. PUH & set packer @ 8465' 3. Pmp 2000 gal of 15% HCL 4. Monitor backside for comm A. If communica 1. PUH 2. Set packer 3. Acdz entir B. If no commun 1. PUH to 84 2. Set RBP @ 3. Acdz uppe C. Release RBP & 5. Swab 6. Acdz w/27,500 gals WF120, pressure of 7000 psi. 7. POH w/pakcer 8. TIH w/prod tbg. TIH w/rods	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456) ation @8300' ee ABO interval w/3000 gals 15% HCL (7000 psi rication 65' @8465' er ABO perfs (8364 – 8456) w/3000 gals 15% HCI & TIH & set RBP @8600', PUH & set packer @83 3000 gals 15% HCL, 13,000 gals 20% SXE & 800 & pump, RD PU. POP	Attach wellbore diagram of proposed completion nax surface pressure @ 5 bpm .00° 0 gals 20% VDA. Attempt 20 bpm at max
13. Describe proposed or complos of starting any proposed wo or recompletion. 1. MIRU PU, ND WH, NU BC 2. PUH & set packer @ 8465' 3. Pmp 2000 gal of 15% HCL 4. Monitor backside for comm A. If communica 1. PUH 2. Set packer 3. Acdz entir B. If no commun 1. PUH to 84 2. Set RBP & 3. Acdz uppe C. Release RBP & 5. Swab 6. Acdz w/27,500 gals WF120, pressure of 7000 psi. 7. POH w/pakcer 8. TIH w/prod tbg. TIH w/rods I hereby certify that the information a	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456) ation @8300' te ABO interval w/3000 gals 15% HCL (7000 psi rication 65' @8465' ter ABO perfs (8364 – 8456) w/3000 gals 15% HCI & TIH & set RBP @8600', PUH & set packer @83 3000 gals 15% HCL, 13,000 gals 20% SXE & 800	Attach wellbore diagram of proposed completion nax surface pressure @ 5 bpm 00' 0 gals 20% VDA. Attempt 20 bpm at max edge and belief. I further certify that any pit or below-
13. Describe proposed or complos of starting any proposed wo or recompletion. 1. MIRU PU, ND WH, NU BC 2. PUH & set packer @ 8465' 3. Pmp 2000 gal of 15% HCL 4. Monitor backside for comm A. If communica 1. PUH 2. Set packer 3. Acdz entir B. If no commun 1. PUH to 84 2. Set RBP & 3. Acdz uppe C. Release RBP & 5. Swab 6. Acdz w/27,500 gals WF120, pressure of 7000 psi. 7. POH w/pakcer 8. TIH w/prod tbg. TIH w/rods I hereby certify that the information a	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456) ation @8300' te ABO interval w/3000 gals 15% HCL (7000 psi rication 65' @8465' ter ABO perfs (8364 – 8456) w/3000 gals 15% HCI & TIH & set RBP @8600', PUH & set packer @85 3000 gals 15% HCL, 13,000 gals 20% SXE & 800 & pump, RD PU. POP above is true and complete to the best of my knowledged according to NMOCD guidelines _, a general permit	Attach wellbore diagram of proposed completion nax surface pressure @ 5 bpm 00' 0 gals 20% VDA. Attempt 20 bpm at max edge and belief. I further certify that any pit or below-
13. Describe proposed or completion of starting any proposed wo or recompletion. 1. MIRU PU, ND WH, NU BC 2. PUH & set packer @ 8465' 3. Pmp 2000 gal of 15% HCL 4. Monitor backside for comm A. If communica 1. PUH 2. Set packer 3. Acdz entir B. If no commun 1. PUH to 84 2. Set RBP & 3. Acdz uppe C. Release RBP & 5. Swab 6. Acdz w/27,500 gals WF120, pressure of 7000 psi. 7. POH w/pakcer 8. TIH w/prod tbg. TIH w/rods I hereby certify that the information a grade tank has been/will be constructed or a series of the set of the	eted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456) ation @8300' the ABO interval w/3000 gals 15% HCL (7000 psi raication 165' to ABO perfs (8364 – 8456) w/3000 gals 15% HCI & TIH & set RBP @8600', PUH & set packer @85 3000 gals 15% HCL, 13,000 gals 20% SXE & 800 & pump, RD PU. POP above is true and complete to the best of my knowled to see the second permit of the set of my knowledged according to NMOCD guidelines , a general permit of the set of the set of my knowledged according to NMOCD guidelines , a general permit of the set	Attach wellbore diagram of proposed completion nax surface pressure @ 5 bpm 00° 0 gals 20% VDA. Attempt 20 bpm at max edge and belief. I further certify that any pit or below- t or an (attached) alternative OCD-approved plan ystDATE8-22-2005
13. Describe proposed or completed of starting any proposed wo or recompletion. 1. MIRU PU, ND WH, NU BC 2. PUH & set packer @ 8465' 3. Pmp 2000 gal of 15% HCL 4. Monitor backside for comm A. If communica 1. PUH 2. Set packer 3. Acdz entir B. If no commun 1. PUH to 84 2. Set RBP @ 3. Acdz uppe C. Release RBP & 5. Swab 6. Acdz w/27,500 gals WF120, pressure of 7000 psi. 7. POH w/pakcer 8. TIH w/prod tbg. TIH w/rods I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE Velma J. K Type or print name Velma F. Gallare For State Use Only	deted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456) ation @8300' the ABO interval w/3000 gals 15% HCL (7000 psi rication 65' @8465' the ABO perfs (8364 - 8456) w/3000 gals 15% HCI & TIH & set RBP @8600', PUH & set packer @85' 3000 gals 15% HCL, 13,000 gals 20% SXE & 800 & pump, RD PU. POP above is true and complete to the best of my knowledged according to NMOCD guidelines \(\D \), a general permitable of the complete to the best of my knowledged according to NMOCD guidelines \(\D \), a general permitable of the complete to the best of my knowledged according to NMOCD guidelines \(\D \), a general permitable of the complete to the best of my knowledged according to NMOCD guidelines \(\D \), a general permitable of the complete to the best of my knowledged according to NMOCD guidelines \(\D \), a general permitable of the complete to the destruction Analysis of the complete to the complete to the destruction of the complete to the complete to the destruction of the complete to t	Attach wellbore diagram of proposed completion ax surface pressure) a 5 bpm oo' o gals 20% VDA. Attempt 20 bpm at max edge and belief. I further certify that any pit or below- t or an (attached) alternative OCD-approved plan of the proposed of the p
13. Describe proposed or completed of starting any proposed wo or recompletion. 1. MIRU PU, ND WH, NU BC 2. PUH & set packer @ 8465' 3. Pmp 2000 gal of 15% HCL 4. Monitor backside for comm A. If communica 1. PUH 2. Set packer 3. Acdz entir B. If no commun 1. PUH to 84 2. Set RBP @ 3. Acdz uppe C. Release RBP & 5. Swab 6. Acdz w/27,500 gals WF120, pressure of 7000 psi. 7. POH w/pakcer 8. TIH w/prod tbg. TIH w/rods I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE Velma J. K Type or print name Velma F. Gallare For State Use Only	deted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456) ation @8300' the ABO interval w/3000 gals 15% HCL (7000 psi rication 65' @8465' the ABO perfs (8364 - 8456) w/3000 gals 15% HCI & TIH & set RBP @8600', PUH & set packer @85' 3000 gals 15% HCL, 13,000 gals 20% SXE & 800 & pump, RD PU. POP above is true and complete to the best of my knowledged according to NMOCD guidelines \(\D \), a general permitable of the complete to the best of my knowledged according to NMOCD guidelines \(\D \), a general permitable of the complete to the best of my knowledged according to NMOCD guidelines \(\D \), a general permitable of the complete to the best of my knowledged according to NMOCD guidelines \(\D \), a general permitable of the complete to the best of my knowledged according to NMOCD guidelines \(\D \), a general permitable of the complete to the destruction Analysis of the complete to the complete to the destruction of the complete to the complete to the destruction of the complete to t	Attach wellbore diagram of proposed completion nax surface pressure) a @ 5 bpm oo' o gals 20% VDA. Attempt 20 bpm at max edge and belief. I further certify that any pit or below- t or an (attached) alternative OCD-approved plan of the proposed of
13. Describe proposed or completed of starting any proposed wo or recompletion. 1. MIRU PU, ND WH, NU BC 2. PUH & set packer @ 8465' 3. Pmp 2000 gal of 15% HCL 4. Monitor backside for comm A. If communica 1. PUH 2. Set packer 3. Acdz entir B. If no commun 1. PUH to 84 2. Set RBP @ 3. Acdz uppe C. Release RBP & 5. Swab 6. Acdz w/27,500 gals WF120, pressure of 7000 psi. 7. POH w/pakcer 8. TIH w/prod tbg. TIH w/rods I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE Velma J. K Type or print name Velma F. Gallare For State Use Only	deted operations. (Clearly state all pertinent details rk). SEE RULE 1103. For Multiple Completions: OP @ 5 bpm, max psi = 7000 unication, ABO perfs (8364-8456) ation @8300' e ABO interval w/3000 gals 15% HCL (7000 psi rication 165' 18465' Er ABO perfs (8364 – 8456) w/3000 gals 15% HCI Ex TIH & set RBP @8600', PUH & set packer @85' 3000 gals 15% HCL, 13,000 gals 20% SXE & 800 & pump, RD PU. POP above is true and complete to the best of my knowledged according to NMOCD guidelines \(\bar{\text{L}} \), a general permitation TITLE Production Analogo CRIGINAL SIGNED E	Attach wellbore diagram of proposed completion nax surface pressure) a @ 5 bpm oo' o gals 20% VDA. Attempt 20 bpm at max edge and belief. I further certify that any pit or below- t or an (attached) alternative OCD-approved plan of the proposed of