

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1960, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
3002511560

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

McBuffington

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Mack Energy Corp.

8. Well No.

1

3. Address of Operator

P.O. Box 960, Artesia, NM 88211

9. Pool name or Wildcat

Langlie Mattox 7 Rvs Qn Grbg.

4. Well Location

Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line

Section 13 Township 25S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-24-03 Rig up unit, RIH w/ 5-1/2" overshoot, latch on parted tbg. Pu-1 up to 50,000 (no success). Try to run 1-3/8" weight bars (set down @ 870').

3-25-03 Pkr. @ 685', sqz. 300 sx cmt. WOC until next day. (plug okayed by Gary Wink w/ OCD). Displaced plug to 800'.

3-26-03 Tag cmt. plug @ 815', mud up hole, perf. 4 holes @ 300'. Sqz. 35 sx cmt. WOC 4 hrs. Tag cmt. plug @ 180', spot 10 sx to surface. RDMO. Cut off wellhead, install dry hole marker, & clean location.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Agent DATE 3/28/03

TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

APPROVED BY [Signature]

OC FIELD REPRESENTATIVE II/STAFF MANAGER

APR 04 2003

CONDITIONS OF APPROVAL, IF ANY: