

Dominion Exploration & Production, Inc.  
14000 Quail Springs Parkway, #600, Oklahoma City, OK 73134-2600



January 26, 2005

30-015-26682

Mr. Bryan Arrant  
Oil Conservation Division, District II Office  
1301 W. Grand Avenue  
Artesia, NM 88210

Re: Boeing Federal 2 Com 1  
1980' FNL & 814' FWL,  
Section 2-23S-26E  
Eddy County, New Mexico

Dear Mr. Arrant:

Sources at Dominion Oklahoma Texas E&P, Inc. have relayed information to me that they believe there will not be enough H<sub>2</sub>S anticipated from the surface to the proposed re-completion of the Bone Springs Formation, to meet the requirements for the submission of a contingency plan per rule 118. Dominion would also like to state that no earth pits will be used in the re-completion of this well, only the use of frac tanks.

Sincerely,  
DOMINION OKLAHOMA TEXAS E & P, INC.

  
Carla Christian  
Regulatory Specialist