Form 3160-5 (August 1999)

DEPARTMENT OF THE INTERIOR N.M. Oil Cons. Division BUREAU OF LAND MANAGEMENT 1625 N. French Dr. 5. La

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

SUNDRY Do not use thi abandoned we	NMNM0145685 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No.				
abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side.					
	LIOATE Guiei maudu	ions on reverse side.			
Type of Well Oil Well	Well Name and No. MultipleSee Attached				
Name of Operator XERIC OIL & GAS COMPAN	NGIE CRAWFORD -Mail: ACrawford@xericoil.com	า	API Well No. MultipleSee Attached		
3a. Address		3b. Phone No. (include area code		10. Field and Pool, or	
P. O. BOX 352 MIDLAND, TX 79702	352 Ph: 915.683.3171 Ext: 235 MILNESAND Fx: 915.683.6348				Exploratory
4. Location of Well (Footage, Sec., 1			11. County or Parish, and State		
MultipleSee Attached				ROOSEVELT C	COUNTY, NM
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, RI	EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION		ТҮРЕ О	TYPE OF ACTION		
Notice of Intent	☐ Acidize	Deepen	Product	ion (Start/Resume)	☐ Water Shut-Off
_	☐ Alter Casing	☐ Fracture Treat	Reclam	ation	☐ Well Integrity
☐ Subsequent Report	☐ Casing Repair	☐ New Construction	□ Recomp	olete	Other
Final Abandonment Notice	☐ Change Plans	Plug and Abandon	Tempor	Temporarily Abandon	
	Convert to Injection	□ Plug Back	□ Water D	Water Disposal	
determined that the site is ready for f 1. MIRU Coiled Tubing Unit. 2. Circulate hole w/9# mud. 3. Spot 25 sx Class C @ 450 4. spot 25 sx Class C @ 2200 5. Spot 25 sx Class C @ 500 6. Cut off casing at surface & 7. Install dryhole marker & cle	0' (356' cement). 0' & tag plug (356' cement) ' (356'cement). spot 5 sx class C @ 70' &		0021222329	bsequent reports shall be new interval, a Form 316 in, have been completed, 22128293037 030 sqqoH 031 131	723456789707
14. I hereby certify that the foregoing is	true and correct.	0125 verified by the BLM We	II Information	Suetom	
Co	For XERIC OIL	& GAS COMPANY, sent to the sing by Armando Lopez on	he Roswell	•	
Name (Printed/Typed) ANGIE CF		•			
					· · · · · · · · · · · · · · · · · · ·
Signature (Electronic S	Submission)	Date 03/28/2	2003		
	THIS SPACE FOR	R FEDERAL OR STATE	OFFICE US	SE	
Approved By ARMANDO A LOPE	TitlePETROLE	EUM ENGINE	ER	Date 04/10/2003	
Conditions of approval, if any, are attache certify that the applicant holds legal or equal which would entitle the applicant to condu-	Subject lease Office Roswell	Office Roswell			
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a c statements or representations as to	rime for any person knowingly an o any matter within its jurisdiction	d willfully to m	ake to any department or	agency of the United

Additional data for EC transaction #20125 that would not fit on the form Wells/Facilities, continued

Agreement	Lease	Well/Fac Name, Number	API Number	Location
NMNM0145685	NMNM0145685	HORTON FED 09	30-041-10105-00-S1	Sec 30 T8S R35E NWSE
NMNM0145685	NMNM0145685	HORTON FED 20	30-041-10114-00-S1	Sec 29 T8S R35E NWNW
NMNM0145685	NMNM0145685	HORTON FED 21	30-041-10115-00-S1	Sec 29 T8S R35E NWSW
NMNM0145685	NMNM0145685	HORTON FED 26	30-041-10120-00-S1	Sec 29 T8S R35E NWNE
NMNM0145685	NMNM0145685	HORTON FED 29	30-041-10123-00-S1	Sec 29 T8S R35E SENE

Amended Plugging Procedures

Xeric Oil & Gas Company Horton Federal #29 1650'/N & 990'/E, Sec. 29-8S-35E Lease NM-0145685

At step 3. set CIBP @ 4640' w/5 sx on top or spot cement plug from 4640'-4770' and tag.

Between Step 3. & Step 4. Spot 25 sx Class C @ 3995' across top of San Andres.

At step 4. perforate 2190' and squeeze cement on backside of 4 ½" then spot 25 sx plug in casing.

At step 5. perforate 4 ½" and squeeze cement to surface then spot 25 sx plug in casing.