

N.M. Oil Cons. Division

1625 N. French Dr.

Hobbs, NM 88240

Form 3160-5
(August 1999)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Saga Petroleum LLC

3a. Address

415 W Wall, Suite 1900, Midland, TX 79701

3b. Phone No. (include area code)

(915)684-4293

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990' FSL & 1700' FWL
Sec 34 (N) T17S, R33E

5. Lease Serial No.

LC062391

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Wyatt "B" Fed #4

9. API Well No.

30-025-01405

10. Field and Pool, or Exploratory Area

Corbin Abo

11. County or Parish, State

Lea
NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☒ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/ Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☒ Other
	☐ Change Plans	☒ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Attempt to recompleate to Queen Sand not successful - producing all wtr - will P&A

TD 8945' - PBTD 8911' - CIBP @ 8600' - perf 3996'-4039' - Pkr @ 3902' perf 8679'-8708'

11-3/4" 32# csg @ 314' w/275 sx, circ surf

4-1/2" 9.5 & 11.6# @ 8945' w/1675 sx

150' Cap CIBP @ 8600' w/35' cmt - 3 sx

100' - plug 5800'-5900' - 10 sx

Set CIBP @ 3950' & cap w/35' cmt - 3 sx


Cut 4-1/2" csg & pull

Set 100' plug @ 1416'-1516' - 30 sx, tag

100' plug @ 264'-364' - 40 sx, tag

50' plug @ surface - 30 sx

Install dry hole marker

APPROVED FOR 3 MONTH PERIODENDING 7-14-03

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Bonnie Husband

Title

Production Analyst

Signature

Bonnie Husband

Date

04/11/2003

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

GWW

OPERATOR: Sager Pet.
 WELL: Wapiti B-H-4

LOCATION: 4900S + 1700W SEC 34-17S-33E

LEASE NO: 117-002391

50' plug @ Surface ⑦

30' plug @ 20' up

2003 APR 14 AM 9:01

BUREAU OF LAND MGMT.
 ROSWELL OFFICE

100' plug @ 264' - 364' ④ 40' up
 (tag)

11 3/4" sg @ 314' w/ 275 SX (circ.) ⑥

Cut 4 1/2" d pull 30' 100' plug @ 1416' - 1516' ④
 3710' Good Cement (tag)

at CIAP @ 3950 + Cap w/ 35' cement ③
 Perf @ 3996' - 4039' 30' up

100' plug @ 5800' - 5900' ② 10' up

35' cement on top ①
 CIAP @ 8600' - 30' up

Perf @ 8679' - 8708'
 PBD @ 8911'

TD 8945' - 4 1/2" sg w/ 1675 SX

Rustler
 1466'

