

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 87210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

30-025-35288

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

26984

7. Lease Name or Unit Agreement Name:

James

8. Well No.

1

9. Pool name or Wildcat

Diamondtail Delaware, SW

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Echo Production, Inc.

3. Address of Operator

PO Box 1210, Graham, TX 76450

4. Well Location

Unit Letter A : 660 feet from the North line and 660 feet from the East line

Section 21 Township 23S Range 32E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3689 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Present Well Data: 13 3/8" csg @ 629' cmt'd to surf, 8 5/8" csg @ 4874' cmt'd to surf & 5 1/2" csg @ 8710' cmt'd to 6308'. Perfs 7928-34', 8167-71', 8450-58', 8482-8500' & 8503-12' shut off w/BP @ 7851'. Open perfs 7418-26'.

Propose to P&A by:

- (1) Load well w/ 9/5# salt gel mud w/ 12.5# gel/barrell
- (2) Set CIBP @ 7380' w/ 4 sx cmt on top (40')
- (3) Cut off and pull casing at free point...+6200'.
- (4) Spot 50 sx cmt +6250' (50' inside pipe) to 6120' (plug to be tagged)
- (5) Spot 50 sx cmt 4930' to 4800' (plug to be tagged)
- (6) Spot 100' plug 1200-1100' (26 sx)
- (7) Spot 100' plug 679-579' (26 sx) (plug to be tagged)
- (8) Spot 15 sx cmt 60' to surface.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Tom Golden

TITLE Operations Manager

DATE 4/14/03

Type or print name

Tom Golden

Telephone No. (940) 549-3292

(This space for State use)

APPROVED BY

Harry W. L. Tink

OC FIELD REPRESENTATIVE II/STAFF MANAGER

TITLE

DATE

Conditions of approval, if any

APR 18 2003

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.