

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	3002532180
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	

<p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b>          (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.</p>		7. Lease Name or Unit Agreement Name SIMS, H. O. -A-
1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	8. Well No. 2
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.	9. Pool Name or Wildcat TEAGUE TUBS DRINKARD <i>Albo M</i>
3. Address of Operator	205 E. Bender, HOBBS, NM 88240	
4. Well Location	Unit Letter <u>I</u> : <u>1980</u> Feet From The <u>S</u> Line and <u>990</u> Feet From The <u>E</u> Line Section <u>33</u> Township <u>22S</u> Range <u>37E</u> NMPM LEA COUNTY	
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	GR-3335, KB-3349	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____	TEMPORARILY ABANDON <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-19-01: MIRU. BLED OFF WELL & UNSEAT PUMP & POH & LD RDS. WELL STARTED FLOWING. LAID LINE TO FRAC TANK & FLOW OFF PRESSURE TO TANK.

4-20-01: PUMP 40 BBLS DN CSG & 25 BBLS DN TBG. NDBOP. TOH W/TBG. RUN GUAGE RING TO 6450'. SET CIBP @ 6450'. LOAD CSG & TEST W/500 PSI-OK. DUMP 35' CMT ON TOP OF CIBP MAKING PBSD @ 6415'.

4-23-01: TIH W/205 JTS TO 6400' & DISPL CSG W/PKR FLUID. PRESS UP ON CSG W/580 PSI & CHART TEST FOR 30 MINS-OK. TOH & LD ALL TBG. FLANGE UP WH & RIG DOWN. CHANGE STATUS TO TEMPORARILY ABANDON. FINAL REPORT

CHART ATTACHED

This Approval of Temporary Abandonment Expires 4/25/08

I hereby certify that the information above is true and complete to the best of my knowledge and belief.


SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 5/3/01

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED Harry W. Wink FIELD REPRESENTATIVE II/STAFF MANAGER DATE APR 25 2003

CONDITIONS OF APPROVAL IF ANY: \_\_\_\_\_ TITLE \_\_\_\_\_



GRAPHIC CONTROLS CORPORATION  
BUFFALO, NEW YORK

H.O. Sims #2  
BR 2221