+Submit 3 Copies to Appropriate

 State of New Mexico Form C 103 Energy, Minerals and Natural Resources Department Revised 1-1-89 District Office OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs, NM S8240 P.O. Box 2088 30-025-10690 DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease FEE X STATE DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil& Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Well **OTHER Injection** Skelly Penrose B Unit 2. Name of Operator 8. Well No. Smith & Marrs 3. Address of Operator 9. Pool name or Wildcat c/o P.O. Box 50820, Midland, TX 79702 Langlie Mattix 7 Rvr-On-Grybg 4. Well Location 660 South 660 Feet From The Line and Feet From The 37E Range **NMPM** Township County 10. Elevation (Show whether DF, RKB. RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **CHANGE PLANS TEMPORARILY ABANDON** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB MIT - T/A Status OTHER: OTHER 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 02-19-03: Rigged up pump truck, pressure tested casing to 520# for 30 minutes-held okay. Chart Attached, T/A test. CIBP: 3470' w/ 35' cecment on top; PBTD: 3435'. This Approval of Temporary Abandonment Expires

I hereby certify that the information above is tru

SIGNATURE

Regulatory Agent

03-05-03

TYPE OR PRINT NAME Ann E. Ritchie

(this space for State Usq)

OC FIELD REPRESENTATIVE II/STAFF MANAGER

