L (1)	●. · · ·		Oil C		1	FORM APPROVED	
Form 3160-5 (August 1999)	UNITED STATE DEPARTMENT OF THE	ΝΙΤΈΡΙΛΡ ''		/-Dist. 2	Exp	MB No. 1004-0135 ires November 30, 2000	
	BUREAU OF LAND MANA	AGEMENTOV I	VV. Gra		NUC C	11 No.)68124	
Do not use th	Y NOTICES AND REPC is form for proposals to III. Use Form 3160-3 (API	drill or to re-	enter an	W 0021	6. If Indian, A	Ilottee or Tribe Name	
SUBMIT IN TR	IPLICATE - Other instr	uctions on re	verse side		7. If Unit or C	CA/Agreement, Name and/o	r No.
1. Type of Well		J			8. Well Name	e and No.	
Oil Well Gas Well Other Plug & Abandon Name of Operator					L. Harris Federal #2		
Yates Petroleum Corporation					9. API Well 1	№. 30-041-2047 <u>4</u>	
3a. Address 105 S. 4th St Artesia, NM 88210 505-748-1471					10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					Todd Wolfcamp 11. County or Parish, State		
1980' FNL & 1980' FEL of Section 22-T7S-R35E							
Unit G, SWNE 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, R					Roosevelt Co., NM		
12. CHECK AP	PROPRIATE BOX(ES) T	O INDICATE N			EPORT, OR (OTHER DATA	
TYPE OF SUBMISSION TYPE OF ACTION							
	Acidize	Deepen	—	Production (Start	t/Resume)	Water Shut-Off Well Integrity	
Notice of Intent	Alter Casing	Fracture Tre		Reclamation Recomplete			
Subsequent Report	 Casing Repair Change Plans 	New Construction		Temporarily Ab	andon		
Final Abandonment Notice	Convert to Injection	Plug Back		Water Disposal			
following completion of the inv testing has been completed. Fi determined that the site is ready 3-22-24-2003 - Migg up tubing equipm 3-26-2003 - POOH 3-27-2003 - Rigg on top at 7555'. Spotted 25 sacks Spotted 25 sacks tubing and tagge 3-28-2003 - Rigg and rigged down psi. POOH with cement from 2051 1831'. POOH with	loved in pulling un- ent and floor. S I with 2-7/8" tube ged up wireline. POOH and rigged Class C Neat cer Class C Neat cer d cement at 4387 ged up wireline. wireline. RIH wireline. packer. RIH oper L-1810'. POOH.	be filed only after init and p it. Nippl Shut down ing. RIH RIH thru d down wir ment from ". POOH w RIH and p ith packer n ended to WOC 4 hour d up wirel	all requirement lugging ed down for nigh open end tubing a eline. 6090-584 4603-436 ith tubi erforate and tub 2051'. s. RIH ine. RI	s, including recla equipment wellhead t. ed to 609 nd tagged Circulate 9'. Pull 2'. POOH ng. Shut d 5-1/2" ing to 16 Spotted with tub	amation, have be and nipp OO'. Shu d CIBP wi ed hole w led up ho d. WOC 4 t well in casing a 681'. Pr 25 sacks ing and t rforated	en completed, and the ope t well in for th 35' of ceme ith plugging m le to 4603'. hours. RIH w for night. t 1985'. POOF essured up to Class C Neat	igged night ent nud. vith 1000
Name (Printed/Typed) DONNA CLACK			Title REGULATORY COMPLIANCE TECHNICIAN				
Signature Anna Clack			Date APRIL 8, 2003				
	THIS SPACE	FOR FEDERA	L OR STATE	COFFICE US	E		
Approved by <u>Conditions</u> of approval, if any, and certify that the applicant holds le which would entitle the applicant to	gal or equitable fifte to those rig o conduct operations thereon.	gins in the subject	Office	PĒ RFO	Da	120293031-7-	23 28 40 11-00
Title 18 U.S.C. Section 1001 and ' States any false, fictitious or fraudu	Title 43 U.S.C. Section 1212, ma ulent statements or representation	ake it a crime for an as as to any matter v	y person know within its jurisdi	ingly and willfull ction.		V	
	GWW					Ки нороз Сстерогог 81 21 91 51	1077

Ì

YATES PETROLEUM CORPORATION L. Harris Federal #2 Section 22-T7S-R35E Roosevelt County, New Mexico

SUNDRY NOTICE CONTINUED:

434'. POOH and rigged down wireline. RIH with packer and tubing and set packer at 126'. Squeezed with 50 sacks Class C Neat cement from 434-334'. WOC. Shut well in for night.

3-29-31-3003 - POOH with packer and tubing. RIH open ended - did not tag. POOH with tubing. RIH with packer and tubing and set packer at 126'. Squeezed with 50 sacks Class C Neat cement from 434-334'. WOC 4 hours. POOH with packer and tubing. RIH with tubing - did not tag. POOH. RIH with packer and tubing and set packer at 126'. Squeezed with 50 sacks Class C Neat cement from 434-334'. WOC. Shut well in for night.

4-1-2003 - RIH with tubing and tagged cement at 447'. POOH. RIH with packer and tubing and set packer at 126'. Squeezed with 50 sacks Class C Neat cement from 434-334'. WOC 4 hours. POOH with packer and tubing. RIH with tubing and tagged at 434'. POOH with tubing. RIH with packer and tubing and set packer at 126'. Squeezed with 50 sacks Class C Neat cement with LCM from 434-334'. WOC. Shut well in for night.

4-2-2003 - POOH with packer. RIH open ended and tagged cement at 307'. POOH with tubing. Rigged up wireline. RIH and perforated 5-1/2" casing at 60'. POOH and rigged down wireline. Circulated 50 sacks Class C Neat cement down 5-1/2" casing and up through 8-5/8" casing. WOC. Shut well in for night.

4-3-2003 - Topped off well with 5 sacks Class C Neat cement. Stayed full. Rigged down pulling unit and plugging equipment. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed April 2, 2003.

Aonna Clack