

Submit 3 Copies To Appropriate District
Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 87210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO. 30-025-09339-00-00

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-1167

7. Lease Name or Unit Agreement Name:

STATE JJ

8. Well No.

1

9. Pool name or Wildcat
LANGLIE MATTIX

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

JOHN H. HENDRIX CORPORATION

3. Address of Operator

P.O. BOX 3040, MIDLAND, TEXAS 79702-3040

4. Well Location

Unit Letter 1 : 1980 feet from the SOUTH line and 660 feet from the EAST line

Section 13

Township 23S

Range 36E

NMPM

County LEA

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3371' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1.) RIG UP P&A EQUIPMENT; DIG AND LINE WORK PIT; NIPPLE UP BOP. 04/23/2003
- 2.) SET CIBP AT 3370'. 04/23/2003
- 3.) CIRCULATE HOLE WITH 9.5# MUD. 04/23/2003
- 4.) CAP CIBP WITH 25 SACKS OF CEMENT. 04/23/2003
- 5.) SPOT 25 SACKS OF CEMENT FROM 3100' TO 3000'. 04/23/2003
- 6.) PERFORATE AT 2115' SQUEEZE WITH 55 SACKS OF CEMENT; DISPLACE TO 2000' TAG AT 1900'. 04/25/2003 AUTHORIZED BY GARY WINK
- 7.) PERFORATE AT 1300' SQUEEZE WITH 55 SACKS OF CEMENT; DISPLACE TOC TO 1200' TAG AT 1150'. 04/25/2003
- 8.) PERFORATE AT 327' SQUEEZE WITH 100 SACKS OF CEMENT; DISPLACE TOC TO 227' TAG AT 250'. 04/25/2003
- 9.) SPOT 20 SACKS OF CEMENT AT 250'.
- 10.) CUT OFF WELLHEAD; SPOT 10 SACK SURFACE PLUG. 04/25/2003
- 11.) INSTALL P&A MARKER. 04/25/2003

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Howard Boatright

TITLE AGENT

DATE 04/29/2003

Type or print name HOWARD BOATRIGHT

Telephone No. (432) 570-5382

(This space for State use)

APPROVED BY *Gary W. Wink* FIELD REPRESENTATIVE II/STAFF MANAGER

MAY 02 2003

Conditions of approval, if any

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.