

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-041-20325
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. K-4128
7. Lease Name or Unit Agreement Name State "CO"
8. Well Number 1
9. OGRID Number
10. Pool name or Wildcat Bluitt (San Andres) Assoc.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

McDonnold Operating, Inc.

3. Address of Operator

505 N. Big Spring, Suite 204, Midland, Texas 79701-4347

4. Well Location

Unit Letter L : 1,980 feet from the South line and 660 feet from the West line
Section 16 Township 8-S Range 38-E NMPM Roosevelt County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3,995 DF

Pit or Below-grade Tank Application ☒ or Closure ☐

Pit type STEEL Depth to Groundwater _____ Distance from nearest fresh water well > 1 mile Distance from nearest surface water > 1 mile

Pit Liner Thickness: STEEL mil Below-Grade Tank: Volume 180 bbls; Construction Material STEEL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8 5/8" 24# csg @ 449' w/ 300 sx circ; 4 1/2" 9.5# csg @ 4,844' w/ 350 sx, TOC 3,700' by TS, open perforations 4,789' - 4,814'

1. Set CIBP @ 4,739'. Circulate hole w/ mud and pump 15 sx C cmt on CIBP.
2. Perforate & squeeze 35 sx C cmt 2,700 - 2,600'. **base of salt plug**
3. Perforate & squeeze 35 sx C cmt 2,300 - 2,200'. WOC & TAG **top of salt plug**
4. Perforate & squeeze 50 sx C cmt 509 - 409'. WOC & TAG **surface casing shoe plug**
5. Circulate 15 sx C cmt 50' to surface. RDMO.
6. Cut off wellhead & anchors, install dry hole marker.

THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE James F. Newman TITLE Engineer DATE 08/29/05

Type or print name James F. Newman, P.E.

For State Use Only

APPROVED BY: Harry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER

Conditions of Approval (if any)

SEP 06 2005