0.1.3.2.3		State of New Mexico	F 0 400
Submit 3 copies to Appropriate District Office	Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-8
D/STRICT'I	OIL CONSI	ERVATION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, N	M 88240	P.O. Box 2088	30-025-04555
DISTRICTII			
P.O. Box Drawer DD, Arte	esia, NM 88210 Santa Fe,	New Mexico 87504-2088	5. Indicate Type of Lease STATE ✓ FEE FEE
DISTRICT III			
1000 Rio Brazos Rd., Azt	ec, NM 87410		6. State Oil / Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI			
			7. Lease Name or Unit Agreement Name
יוט	(FORM C-101) FOR SUCH P	ROPOSALS.	EUNICE MONUMENT SOUTH UNIT
Type of Well: OIL WEL	GAS _		
2. Name of Operator	WELL U OTHER		8. Well No.
2 o. opolatoi	CHEVRON USA INC		323
3. Address of Operator	15 SMITH ROAD, MIDLAND, TX	79705	9. Pool Name or Wildcat EUNICE MONUMENT GRAYBURG
4. Well Location			EUNICE MONUMENT GRATBURG
Unit Letter	<u> 1980'</u> Feet Fro	m The <u>SOUTH</u> Line and <u>660'</u>	Feet From The <u>EAST</u> Line
Section 8	Township 21-S	Range 36-E N	MPMLEA COUNTY
	10. Elevation (Show v	whether DF, RKB, RT,GR, etc.) 3608' GL	
11.	Check Appropriate Box to	Indicate Nature of Notice, Report	, or Other Data
NOTICE OF	FINTENTION TO:	SI	JBSEQUENT REPORT OF:
PERFORM REMEDIAL W	ORK PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDO	CHANGE PLANS	COMMENCE DRILLING OP	ERATION PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEMEI	NT JOB
OTHER:	REQUEST TA APPROVAL	OTHER:	
CHEVRON U.S.A. INC.	RULE 1103. NTENDS TO TEMPORARILY ABAN		ates, including estimated date of starting any
			030 500 500 500 500 500 500 500
I hereby certify that the information abo	ve is true and complete to the best of my knowledge and b	eller. FITLE Regulatory Specialist	DATE 5/6/2003

APPROVED HOLL W. W. CONDITIONS OF APPROVAL, IF ANY:

TYPE OR PRINT NAME

OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

Telephone No.

Denise Leake

915-687-7375

EMSU # 323 API # 30-025-04555 1980' FSL & 660' FEL S8, T21S, R36E, & Unit I Eunice Monument South Unit Lea County, New Mexico

PROCEDURE TO TEMPORARILY ABANDON WELL:

Notify OCD/BLM 24 hrs prior to work commencing.

- 1. Verify anchors have been set & tested.
- 2. MIRU PU. ND WH. NU BOP.
- 3. Pull rods, pump, and 2-7/8" tubing.
- 4. TIH w/6-1/8" bit, csg scraper, & WS. Make bit trip to 3700'. POH.
- 5. Set CIBP @ 3650'. Dump 8 sx Class 'C' cmt on CIBP.
- 6. TIH w/WS to TOC. Circulate csg w/corrosion inhibited pkr fluid. TOH.
- 7. Perform MIT (500 PSI for 30 min.).
- 8. ND BOP. NU WH. RD PU.
- 9. Clean and clear location.

Kevin Hickey 432-687-7260

Chevron

WELL DATA SHEET

