
State of New Mexico

Submit 3 copies to Appropriate District Office	Energy, Minerals and Natural	Resources Department		Form C-103 Revised 1-1-8
DISTRICT I	OIL CONSERVATI	ON DIVISION	WELL API NO.	
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 20		30-025-06324	
DISTRICT II	Santa Eo New Mexic		5. Indicate Type of Lease	
P.O. Box Drawer DD, Artesia, NM 88210) Carita I C, I vew IVIEXI	50 07 504-2000	STATE V	FEE
DISTRICT III			6. State Oil / Gas Lease No.	
1000 Rio Brazos Rd., Aztec, NM 87410			o. otate our das Edase No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.			7. Lease Name or Unit Agreement Na EUNICE MONUMENT SOUTH U	
1. Type of Well: OIL GAS WELL WE		CTION WELL		
2. Name of Operator CHEVRON	USA INC		8. Well No. 156	
Address of Operator 15 SMITH ROAD, MIDLAND, TX 79705		9. Pool Name or Wildcat EUNICE MONUMENT GRAYBURG		
4. Well Location				
Unit Letter K:	1980' Feet From The SOL	JTH Line and 1880'	Feet From The WEST L	ine
Section 32	Township20-S	Range 37-E NN	MPMLEA_CO	UNTY
	10. Elevation (Show whether DF, RK	B, RT,GR, etc.) 3541' GL		
11. Check A	appropriate Box to Indicate Na	ature of Notice, Report	, or Other Data	
NOTICE OF INTENTION	ON TO:	St	JBSEQUENT REPORT O	F:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	☐ ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP	ERATION PLUG AND ABANDO	NMENT
PULL OR ALTER CASING	_	CASING TEST AND CEMEN	AOL TA	_,
OTHER: REQUEST	TA APPROVAL	OTHER:		
		OTTEK.		
 Describe Proposed or Completed Opproposed work) SEE RULE 1103. 	perations (Clearly state all pertinent	details, and give pertinent d	ates, including estimated date of sta	arting any

CHEVRON U.S.A. INC. INTENDS TO TEMPORARILY ABANDON THE SUBJECT WELL. THE INTENDED PROCEDURE AND WELLBORE DIAGRAM IS ATTACHED FOR YOUR APPROVAL.



I hereby certify that the information above is to	ue and complete to the best of my knowledge and belief.		
SIGNATURE		DATE	6/6/2003
TYPE OR PRINT NAME	Denise Leake	Telephone No.	915-687-7375
	^		

TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER

MAY 1 5 2003

EMSU # 156 API # 30-025-06324 1980' FNL & 560' FWL S32, T20S, R37E, & Unit K Eunice Monument South Unit Lea County, New Mexico

PROCEDURE TO TEMPORARILY ABANDON WELL:

Notify OCD/BLM 24 hrs prior to work commencing.

- 1. Verify anchors have been set & tested.
- 2. MIRU PU. ND WH. NU BOP.
- 3. Pull 2-3/8" tubing and packer @ 3627'. PU 2-7/8" workstring.
- 4. TIH w/4-3/4" bit, csg scraper, & WS. Make bit trip to 3840'. POH.
- 5. Set CIBP @ 3580'. Dump 5 sx Class 'C' cmt on CIBP.
- 6. TIH w/WS to TOC. Circulate csg w/corrosion inhibited pkr fluid. TOH.
- 7. Perform MIT (500 PSI for 30 min.).
- 8. ND BOP. NU WH. RD PU.
- 9. Clean and clear location.

Kevin Hickey 432-687-7260

Chevron

WELL DATA SHEET

