

District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.	30-025-29325
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Central Corbin Queen Unit
8. Well No.	201
9. Pool name or Wildcat	Corbin Queen
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other WIW ☐

2. Name of Operator
Saga Petroleum LLC

3. Address of Operator
415 W. Wall, Suite 1900
Midland, TX 79701

4. Well Location
Unit Letter O : 660 feet from the S line and 1980 feet from the E line
Section 4 Township 18S Range 33E NMPM County Lea

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data


NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: Press test for WIW after HIT repair <input checked="" type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.

4-24-03 Blow well to pit, ND WH, NU BOP, release pkr, TOO H w/tbg & pkr, bullplug tbg, test every row to 3000 psi, HIT #127, POOH, PU pkr, RIH, ND BOP, NUWH, circ pkr fluid, NDWH, set pkr, NUWH, test csg to 500 psi-test good, put well on inj, no OCD witness

2-3/8" x 5-1/2" AD-1 pkr, 131 (4138') 2-3/8" cmt lined tbg

Chart attached



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE Production Analyst DATE 05/06/2003

Type or print name Bonnie Husband

Telephone No. (432)684-4293

(This space for State use)

APPROVED BY Gary W. Wink ORIGINAL SIGNED BY GARY W. WINK
Conditions of approval, if any: OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE MAY 15 2003

