Office	State of New Mexico	Form C-103
District I Energy 1625 N. French Dr., Hobbs, NM 88240	gy, Minerals and Natural Resources	May 27, 2004 WELL API NO.
District II	CONSERVATION DIVISION	30-025-10412
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	STATE FEE X 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		6. 5 5 5 5 5 5 6
SUNDRY NOTICES AND		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Will Cary
PROPOSALS.)		8. Well Number 7
1. Type of Well: Oil Well X Gas Well Other 2. Name of Operator		9. OGRID Number
John H. Hendrix Corporation		012024
3. Address of Operator P. O. Box 3040 Midland, TX 79702-3040		10. Pool name or Wildcat
4. Well Location	3040	Drinkard Polinebry 6660
Unit Letter_F :_ 1874	feet from the North line and 208	feet from the West line
NAME OF COLUMN STATE OF THE PROPERTY OF THE PR	Township 22S Range 37E	NMPM CountyLea
11. Elevar	tion (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application or Closure	D1	
Pit typeDepth to Groundwater_65D	istance from nearest fresh water well Dist	ance from nearest surface water
Pit Liner Thickness: mil Below-G	rade Tank: Volume bbls; Co	nstruction Material
12. Check Appropriat	e Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTIO	N TO: SUB:	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AN	D ABANDON 🔼 REMEDIAL WOR	
TEMPORARILY ABANDON ☐ CHANGE PULL OR ALTER CASING ☐ MULTIPL		
	E COMPL CASING/CEMENT	T JOB L
OTHER:	OTHER:	
of starting any proposed work). SEE R	ULE 1103. For Multiple Completions: Att	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
or recompletion.		The proposed completion
1. Set 25 sx. cement cap on CIBP at 5900'. Ste	el pits will be used.	
/ Life hole w/ mud ladden thrid		
 Circ. hole w/ mud ladden fluid. Set CIBP at 5400' + 25 sx. cap to cover perfi 	s. 5453 - 5754'.	
3. Set CIBP at 5400' + 25 sx. cap to cover perf. 4. Perf. 5-1/2" at 2300' and attempt to circ. cerr	s. 5453 - 5754'. nent to surface leaving 5-1/2" csg. full of ce	ment fr. 2300' to surface. (500 sx.)
3. Set CIBP at 5400' + 25 sx, cap to cover perf	s. 5453 - 5754'. nent to surface leaving 5-1/2" csg. full of ce	ment fr. 2300' to surface. (500 sx.)
3. Set CIBP at 5400' + 25 sx. cap to cover perf. 4. Perf. 5-1/2" at 2300' and attempt to circ. cerr	Deadline to plug and abandon to	
 3. Set CIBP at 5400' + 25 sx. cap to cover perf. 4. Perf. 5-1/2" at 2300' and attempt to circ. cem 5. Cut well head and install dry hole marker. 	Deadline to plug and abandon to December 10, 2005.	his well is
 Set CIBP at 5400' + 25 sx. cap to cover perf. Perf. 5-1/2" at 2300' and attempt to circ. cem Cut well head and install dry hole marker. 	Deadline to plug and abandon the December 10, 2005.	his well is
3. Set CIBP at 5400' + 25 sx. cap to cover perfit. 4. Perf. 5-1/2" at 2300' and attempt to circ. cen 5. Cut well head and install dry hole marker. THE OIL CONSERVATION	Deadline to plug and abandon to December 10, 2005.	his well is N
3. Set CIBP at 5400' + 25 sx. cap to cover perfit. 4. Perf. 5-1/2" at 2300' and attempt to circ. cen 5. Cut well head and install dry hole marker. THE OIL CONSERVATION	Deadline to plug and abandon to December 10, 2005.	his well is N
3. Set CIBP at 5400' + 25 sx. cap to cover perfit. 4. Perf. 5-1/2" at 2300' and attempt to circ. cen 5. Cut well head and install dry hole marker. THE OIL CONSERVATION	Deadline to plug and abandon to December 10, 2005.	his well is N
3. Set CIBP at 5400' + 25 sx. cap to cover perfit. 4. Perf. 5-1/2" at 2300' and attempt to circ. cen 5. Cut well head and install dry hole marker. THE OIL CONSERVATION	Deadline to plug and abandon to December 10, 2005.	his well is
3. Set CIBP at 5400' + 25 sx. cap to cover perf. 4. Perf. 5-1/2" at 2300' and attempt to circ. cen 5. Cut well head and install dry hole marker. THE OIL CONSERVATION BE NOTIFIED 24 HOURS BEGINNING OF PLUGGIN	Deadline to plug and abandon to December 10, 2005. N DIVISION MUST PRIOR TO THE GOPERATIONS.	his well is N R R R R R R R R R R R R
3. Set CIBP at 5400' + 25 sx. cap to cover perfit. 4. Perf. 5-1/2" at 2300' and attempt to circ. cent. 5. Cut well head and install dry hole marker. THE OIL CONSERVATION BE NOTIFIED 24 HOURS BEGINNING OF PLUGGIN I hereby certify that the information above is true.	Deadline to plug and abandon to December 10, 2005. N DIVISION MUST OPERATIONS.	his well is N Zergrand belief. I further coefficient and it as below.
3. Set CIBP at 5400' + 25 sx. cap to cover perf. 4. Perf. 5-1/2" at 2300' and attempt to circ. cem 5. Cut well head and install dry hole marker. THE OIL CONSERVATION BE NOTIFIED 24 HOURS BEGINNING OF PLUGGIN I hereby certify that the information above is true grade tank has benefit that the constructed or closed according.	Deadline to plug and abandon to December 10, 2005. N DIVISION MUST OPERATIONS. The and complete to the best of my knowledge and to NMOCD guidelines , a general permit of the second of the second operation.	his well is N Zergrand belief. I further coefficient and it as below.
3. Set CIBP at 5400' + 25 sx. cap to cover perfit. 4. Perf. 5-1/2" at 2300' and attempt to circ. cent. 5. Cut well head and install dry hole marker. THE OIL CONSERVATION BE NOTIFIED 24 HOURS BEGINNING OF PLUGGIN I hereby certify that the information above is true.	Deadline to plug and abandon to December 10, 2005. N DIVISION MUST OPERATIONS.	his well is N Zergrand belief. I further coefficient and it as below.
3. Set CIBP at 5400' + 25 sx. cap to cover perf. 4. Perf. 5-1/2" at 2300' and attempt to circ. cem 5. Cut well head and install dry hole marker. THE OIL CONSERVATION BE NOTIFIED 24 HOURS BEGINNING OF PLUGGIN I hereby certify that the information above is true grade tank has been/will be constructed or closed accord. SIGNATURE	Deadline to plug and abandon to December 10, 2005. N DIVISION MUST PRIOR TO THE GOPERATIONS. e and complete to the best of my knowledge and to NMOCD guidelines , a general permit of TITLE Vice President	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
3. Set CIBP at 5400' + 25 sx. cap to cover perfit. 4. Perf. 5-1/2" at 2300' and attempt to circ. cem 5. Cut well head and install dry hole marker. THE OIL CONSERVATION BE NOTIFIED 24 HOURS BEGINNING OF PLUGGIN I hereby certify that the information above is true grade tank has benavirible constructed or closed according to the	Deadline to plug and abandon to December 10, 2005. N DIVISION MUST PRIDR TO THE GOPERATIONS. e and complete to the best of my knowledge and to NMOCD guidelines , a general permit TITLE Vice President	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 08/31/2005 Telephone No. (432)684-6631
3. Set CIBP at 5400' + 25 sx. cap to cover perfit. 4. Perf. 5-1/2" at 2300' and attempt to circ. cem 5. Cut well head and install dry hole marker. THE OIL CONSERVATION BE NOTIFIED 24 HOURS BEGINNING OF PLUGGIN I hereby certify that the information above is true grade tank has benawid be constructed or closed accord SIGNATURE Type or print name Ronnie H. Westbrook For State Use Only APPROVED BY:	Deadline to plug and abandon to December 10, 2005. N DIVISION MUST PRIDE TO THE GOPERATIONS. e and complete to the best of my knowledge and to NMOCD guidelines , a general permit of TITLE Vice President	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 08/31/2005 Telephone No. (432)684-6631
3. Set CIBP at 5400' + 25 sx. cap to cover perfit. 4. Perf. 5-1/2" at 2300' and attempt to circ. cem 5. Cut well head and install dry hole marker. THE OIL CONSERVATION BE NOTIFIED 24 HOURS BEGINNING OF PLUGGIN I hereby certify that the information above is true grade tank has benavirible constructed or closed according to the	Deadline to plug and abandon to December 10, 2005. N DIVISION MUST PRIDR TO THE GOPERATIONS. e and complete to the best of my knowledge and to NMOCD guidelines , a general permit TITLE Vice President	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 08/31/2005 Telephone No. (432)684-6631
3. Set CIBP at 5400' + 25 sx. cap to cover perf. 4. Perf. 5-1/2" at 2300' and attempt to circ. cem 5. Cut well head and install dry hole marker. THE OIL CONSERVATION BE NOTIFIED 24 HOURS BEGINNING OF PLUGGIN I hereby certify that the information above is true grade tank has be parawil be constructed or closed accord SIGNATURE Type or print name Ronnie H. Westbrook For State Use Only APPROVED BY:	Deadline to plug and abandon to December 10, 2005. N DIVISION MUST PRIDR TO THE GOPERATIONS. e and complete to the best of my knowledge and to NMOCD guidelines , a general permit TITLE Vice President	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 08/31/2005 Telephone No. (432)684-6631
3. Set CIBP at 5400' + 25 sx. cap to cover perf. 4. Perf. 5-1/2" at 2300' and attempt to circ. cem 5. Cut well head and install dry hole marker. THE OIL CONSERVATION BE NOTIFIED 24 HOURS BEGINNING OF PLUGGIN I hereby certify that the information above is true grade tank has be parawil be constructed or closed accord SIGNATURE Type or print name Ronnie H. Westbrook For State Use Only APPROVED BY:	Deadline to plug and abandon to December 10, 2005. N DIVISION MUST PRIDR TO THE GOPERATIONS. e and complete to the best of my knowledge and to NMOCD guidelines , a general permit TITLE Vice President	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 08/31/2005 Telephone No. (432)684-6631
3. Set CIBP at 5400' + 25 sx. cap to cover perf. 4. Perf. 5-1/2" at 2300' and attempt to circ. cem 5. Cut well head and install dry hole marker. THE OIL CONSERVATION BE NOTIFIED 24 HOURS BEGINNING OF PLUGGIN I hereby certify that the information above is true grade tank has be parawil be constructed or closed accord SIGNATURE Type or print name Ronnie H. Westbrook For State Use Only APPROVED BY:	Deadline to plug and abandon to December 10, 2005. N DIVISION MUST PRIDR TO THE GOPERATIONS. e and complete to the best of my knowledge and to NMOCD guidelines , a general permit TITLE Vice President	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 08/31/2005 Telephone No. (432)684-6631
3. Set CIBP at 5400' + 25 sx. cap to cover perfit. 4. Perf. 5-1/2" at 2300' and attempt to circ. cem 5. Cut well head and install dry hole marker. THE OIL CONSERVATION BE NOTIFIED 24 HOURS BEGINNING OF PLUGGIN I hereby certify that the information above is true grade tank has bera/will be constructed or closed accord. SIGNATURE Type or print name Ronnie H. Westbrook For State Use Only APPROVED BY: Conditions of Approval (if any):	Deadline to plug and abandon to December 10, 2005. N DIVISION MUST PRIOR TO THE GOPERATIONS. TITLE Vice President TITLE Vice President TITLE VICE PRESENTATIVE IL/STAFF MANAFIELD REPRESENTATIVE IL/STAFF MANA	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 08/31/2005 Telephone No. (432)684-6631 SEP 0 7 2005
3. Set CIBP at 5400' + 25 sx. cap to cover perfit. 4. Perf. 5-1/2" at 2300' and attempt to circ. cem 5. Cut well head and install dry hole marker. THE OIL CONSERVATION BE NOTIFIED 24 HOURS BEGINNING OF PLUGGIN I hereby certify that the information above is true grade tank has bera/will be constructed or closed accord. SIGNATURE Type or print name Ronnie H. Westbrook For State Use Only APPROVED BY: Conditions of Approval (if any):	Deadline to plug and abandon to December 10, 2005. N DIVISION MUST PRIDR TO THE GOPERATIONS. e and complete to the best of my knowledge and to NMOCD guidelines , a general permit TITLE Vice President	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 08/31/2005 Telephone No. (432)684-6631 SEP 0 7 2005
3. Set CIBP at 5400' + 25 sx. cap to cover perfit. 4. Perf. 5-1/2" at 2300' and attempt to circ. cem 5. Cut well head and install dry hole marker. THE OIL CONSERVATION BE NOTIFIED 24 HOURS BEGINNING OF PLUGGIN I hereby certify that the information above is true grade tank has bera/will be constructed or closed accord. SIGNATURE Type or print name Ronnie H. Westbrook For State Use Only APPROVED BY: Conditions of Approval (if any):	Deadline to plug and abandon to December 10, 2005. N DIVISION MUST PRIOR TO THE GOPERATIONS. TITLE Vice President TITLE Vice President TITLE VICE PRESENTATIVE IL/STAFF MANAFIELD REPRESENTATIVE IL/STAFF MANA	c and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 08/31/2005 Telephone No. (432)684-6631 SEP 0 7 2005
3. Set CIBP at 5400' + 25 sx. cap to cover perfit. 4. Perf. 5-1/2" at 2300' and attempt to circ. cem 5. Cut well head and install dry hole marker. THE OIL CONSERVATION BE NOTIFIED 24 HOURS BEGINNING OF PLUGGIN I hereby certify that the information above is true grade tank has bera/will be constructed or closed accord. SIGNATURE Type or print name Ronnie H. Westbrook For State Use Only APPROVED BY: Conditions of Approval (if any):	Deadline to plug and abandon to December 10, 2005. N DIVISION MUST PRIOR TO THE GOPERATIONS. TITLE Vice President TITLE Vice President TITLE VICE PRESENTATIVE IL/STAFF MANAFIELD REPRESENTATIVE IL/STAFF MANA	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 08/31/2005 Telephone No. (432)684-6631 SEP 0 7 2005 TIME : 09/89/2005 06:23 NAME : EMNRD OCD FAX : 5053930720
3. Set CIBP at 5400' + 25 sx. cap to cover perfit. 4. Perf. 5-1/2" at 2300' and attempt to circ. cem 5. Cut well head and install dry hole marker. THE OIL CONSERVATION BE NOTIFIED 24 HOURS BEGINNING OF PLUGGIN I hereby certify that the information above is true grade tank has bera/will be constructed or closed accord. SIGNATURE Type or print name Ronnie H. Westbrook For State Use Only APPROVED BY: Conditions of Approval (if any):	Deadline to plug and abandon to December 10, 2005. N DIVISION MUST PRIOR TO THE GOPERATIONS. TITLE Vice President TITLE Vice President TITLE VICE PRESENTATIVE IL/STAFF MANAFIELD REPRESENTATIVE IL/STAFF MANA	tand belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 08/31/2005 Telephone No. (432)684-6631 SEP 7 2005 TIME : 89/89/2005 86:23 NAME : EMNRD OCD

DATE, TIME FAX NO. /NAME DURATION PAGE(S) RESULT 09/09 06:22 14325847317 00:00:40 02 CK STANDARD

Submit 3 Copies To Appropriate District Office District I	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 May 27, 2004		
1625 N. French Dr., Hobbs, NM 88240	2.1015), Illinoidis dila Patarai Resources	WELL API NO.		
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-104 12		
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE X		
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Will Cary		
1. Type of Well: Oil Well X Gas Well Other		8. Well Number 7		
Name of Operator John H. Hendrix Corporation		9. OGRID Number 012024		
3. Address of Operator P. O. Box 3040 Midland, TX 79702-3040		10. Pool name or Wildcat Drinkard		
4. Well Location				
	feet from the North line and 20	86feet from theWestline		
Section 22	Township 22S Range 37E	NMPM CountyLea		
	11. Elevation (Show whether DR, RKB, RT, GR, etc., 3371' DF			
Pit or Below-grade Tank Application 🔲 o				
Pit typeDepth to Groundw	ater 65 Distance from nearest fresh water well Dist	ance from nearest surface water		
Pit Liner Thickness: mil		onstruction Material		
12. Check	Appropriate Box to Indicate Nature of Notice,	Report or Other Data		
		•		
NOTICE OF IN		SEQUENT REPORT OF:		
TEMPORARILY ABANDON	PLUG AND ABANDON 🗵 REMEDIAL WOR CHANGE PLANS 🗆 COMMENCE DRI			
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMENT	_		
OTHER: 13 Describe proposed or comp	OTHER: letted operations. (Clearly state all pertinent details, and	d aire a continue to the conti		
of starting any proposed we or recompletion.	ork). SEE RULE 1103. For Multiple Completions: At	tach wellbore diagram of proposed completion		
 Set 25 sx. cement cap on CIBP at 2. Circ. hole w/ mud ladden fluid. 	at 5900'. Steel pits will be used.			
3. Set CIBP at 5400' + 25 sx. cap t	o cover perfs. 5453 - 5754'.			
 4. Perf. 5-1/2" at 2300' and attempt to circ. cement to surface leaving 5-1/2" csg. full of cement fr. 2300' to surface. (500 sx.) 5. Cut well head and install dry hole marker. 				
5. Cut wen nead and histain dry no.	e marker.			
		and the second of		
		18=30127925		
		150°		
		(S & S & S		
THE OIL CON	SERVATION DIVISION MUST			
BE NOTIFIEI	24 HOURS PRIOR TO THE			
BEGINNING (F PLUGGING OPERATIONS.	~ ``\'%		
		and the second second		
hereby certify that the information	shove is two and complete to the best for the left	26252625		
grade tank has been will be constructed or	above is true and complete to the best of my knowledge closed according to NMOCD guidelines , a general permit	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan		
SIGNATURE HERWAN	TITLE Vice President	DATE 08/31/2005		
Гуре or print name Ronnie H. West	brook A E	Telephone No. (432)684-6631 DATE DATE		
For State Use Only	brook E-mail address:	1 elephone No. (432)684-6631		
2/) /) b	AFF MAI		
APPROVED BY: ACCOUNTY Conditions of Approval (if any):	OF FIELD REPRESENTATIVE			
CONTROLS OF A ODEOVALUE AMVI.		SEP 0 7 2005		

المراجعة والمراجعة والمراج

Will Cary No. 7

1874 FNL & 2086 FWI See JJ TJJS-R37E. Lea County N. M.

E/w: 3373

Top of coment 2505

Top of coment 2505

Cernent Circ.

Cernent Circ.

Cernent Circ.

Per order 5003

Pest 3050-51-10050 Pest 3300-01 Pest 34'10-41

Top of cement 3490' by

PROPOSED

Pers 5977-6186-

6414

5 1/2" at 64 14. 350 sx

Parts 6280-6305.

Ck ux 6300'- sqt - 200 5x

TD 6467