

Submit 3 Copies To Appropriate District
Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 87210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO. 30-025-09217-00-00
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1167
7. Lease Name or Unit Agreement Name: STATE JG
8. Well No. 2
9. Pool name or Wildcat LANGLIE MATTIX

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>
2. Name of Operator JOHN H. HENDRIX CORPORATION
3. Address of Operator PO BOX 3040; MIDLAND, TEXAS 79702-3040
4. Well Location Unit Letter <u>J</u> : <u>1650</u> feet from the <u>EAST</u> line and <u>2310</u> feet from the <u>SOUTH</u> line Section <u>2</u> Township <u>23S</u> Range <u>36E</u> NMPM LEA County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1.) RIG UP P & A EQUIPMENT; DIG AND LINE WORK PIT; NIPPLE UP BOP. 05/09/2003
- 2.) SET CIBP AT 3525'. 05/12/2003
- 3.) CAP CIBP WITH 25 SACKS OF CEMENT. 05/12/2003
- 4.) SQUEEZE 35 SACKS OF CEMENT UNDER PACKER; PACKER SET AT 2800'; DISPLACE TO 3050'; WOC. 05/12/2003
TAG AT 3135'; APPROVED BY BUDDY HILL - OCD. 05/13/2003
- 5.) CIRCULATE HOLE WITH 9.5# MUD.
- 6.) PERFORATE AT 2724'; COULD NOT SQUEEZE; SPOT 25 SACKS OF CEMENT AT 2775'; WOC; TAG AT 2545'; APPROVED BY BUDDY HILL - OCD. 05/13/2003
- 7.) PERFORATE AT 1300'; SQUEEZE 55 SACKS OF CEMENT; DISPLACE TOC TO 1200'; DID NOT TAG. 05/13/2003
- 8.) RESQUEEZE WITH 55 SACKS OF CEMENT; DISPLACE TOC TO 1200'; TAG AT 1290'. 05/14/2003
- 9.) SPOT 15 SACKS OF CEMENT AT 1290'.
- 10.) PERFORATE AT 300'; SQUEEZE WITH 100 SACKS OF CEMENT; DISPLACE TOC TO 200'; TAG AT 270'. 05/15/2003
- 11.) SPOT 30 SACKS OF CEMENT AT 270'. 05/15/2003
- 12.) CUT OFF WELLHEAD; SPOT 10 SACK SURFACE PLUG. 05/15/2003
- 13.) INSTALL P & A MARKER. 05/15/2003

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Howard Boatright TITLE AGENT DATE 05/19/2003

Type or print name HOWARD BOATRIGHT

Telephone No. (432)570-5382

(This space for State use)

APPROVED BY Harry W. Wink FIELD REPRESENTATIVE II/STAFF MANAGER

Conditions of approval, if any: MAY 22 2003

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.