Submit 3 Copies To Appropriate District Office State of New Mo	evice		
Office State of New Monthstell Energy, Minerals and National Energy	Form C-103		
1625 N. French Dr., Hobbs, NM 87240 District II	WELL API NO.		
811 South First, Artesia, NM 87210 OIL CONSERVATION	I DIVISION 30-025-20209		
District III 1000 Rio Brazos Rd., Aztec, NM 87410 2040 South Paci	heco 5. Indicate Type of Lease		
District IV Santa Fe. NM 8'	7505 STATE X FEE		
2040 South Pacheco, Santa Fe, NM 87505	6. State Oil & Gas Lease No. E-8454		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLD DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)	7. Lease Name or Unit Agreement Name:		
1. Type of Well: Oil Well X Gas Well Other	Mesa Queen		
2. Name of Operator Xeric Oil & Gas Corporation	8 Well No		
3. Address of Operator P. O. Box 352			
Midland TY 70702	9. Pool name or Wildcat Mesa Oueen Associated		
4. Well Location	nesa oueen Associated		
Unit Letter A: 660 feet from the North	line and 660 feet from the East line		
Section 16 Township 16S Ra	inge 32E NMPM Lea County		
10. Elevation (Show whether D)	R, RKB, RT, GR, etc.)		
11. Check Appropriate Box to Indicate N			
NOTICE OF INTENTION TO:	ature of Notice, Report or Other Data		
PERFORM REMEDIAL WORK PLUG AND ABANDON	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING TO		
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND		
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TEST AND ABANDONMENT CEMENT JOB		
OTHER:	OTHER:		
12. Describe proposed or completed operations. (Clearly state all per	tinant details and all all and all and all and all and all and all and all all all all all and all all all all all all all all all al		
Proposed work). SEE KOLE 1103. For Milliple (Completions: Attach wellbore diagram of proposed completion		
or recompilation. 1) MIRU Pulling Unit.	O Pro-Leave sombiotion		
2) Spot 25 sx plug @ 3300' & tag.	2245		
3) Spot 25 sx plug @ 1300' & tag.	37 123456		
4) Cut casing @ 600' & lay down.			
5) Spot 25 sx, 50' in and out of stub & tag.			
6) Spot 25 sx @ 50' & bring to surface.	2		
7) RD & install dry hole marker.	7000		
	10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
THE COMMISSION	MUST BE NOTIFIED 24 2		
HOURS PRIOR TO	THE BEGINNING OF COLORS FOR THE CALORS		
TO BE APPROVED.			
I hereby certify that the information above is true and complete to the !	pest of my knowledge and belief		
	Dec Local Control of the Control of		
Aligie Crawford ()	Production Analyst DATE 5/27/03 915-683-3171		
Type or print name (This space for State use)	713-083-31/1 Telephone No.		
APPPROVED BY Law W. Wink OC FIELD REPRESENTATIVE II/STAFF MANAGER MAY 3 0 200 Conditions of approval, if any			

.

XERIC OIL & GAS CORP
WELLBORE DIAGRAM

WELL: Mesa Queen Unit #3
COUNTY: Lea
STATE: NM

HOLE SIZE: 11" (CASING: 85/4"@353"	
CASING: 85/1"@353"	
CEMBUTED WITH: 2005	<u> </u>
CEMENT TOP: <u>Suit</u>	. 1

TUBING: _____

PUMP : ____

PACKER:

HOLE SIZE: 63/4'

CASING: 41/2" @3474

CEMENTED WITH: 1255X

CEMENT TOP: 1663'

