

District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO. 30-025-20564
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name:  Mesa Queen
8. Well No. 19
9. Pool name or Wildcat Mesa Queen Associated

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
Xeric Oil & Gas Corporation

3. Address of Operator  
P. O. Box 352  
Midland, TX 79702

4. Well Location  
Unit Letter 0 : 1650 feet from the East line and 990 feet from the South line  
Section 17 Township 16S Range 32E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- 1) MIRU Pulling Unit.
- 2) Spot 25 sx plug @ 3300' & tag.
- 3) Spot 25 sx plug @ 1300' & tag.
- 4) Cut casing @ 600' & lay down.
- 5) Spot 25 sx, 50' in and out of stub & tag.
- 6) Spot 25 sx @ 50' & bring to surface.
- 7) RD & install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angie Crawford TITLE Production Analyst DATE 5/27/03  
Type or print name Angie Crawford Telephone No. 915-683-3171

(This space for State use) **OC FIELD REPRESENTATIVE II/STAFF MANAGER**  
APPROVED BY Harry W. Wink TITLE  DATE MAY 30 2003  
Conditions of approval, if any:

XERIC OIL & GAS CORP.  
WELLBORE DIAGRAM

WELL: Mesa Queen #19

COUNTY: Lea

STATE: NM

HOLE SIZE: 11"  
CASING: 8 5/8" @ 385'  
CEMENTED WITH: 175 SX  
CEMENT TOP: Surf.

TUBING: \_\_\_\_\_  
RODS: \_\_\_\_\_  
PUMP: \_\_\_\_\_  
PACKER: \_\_\_\_\_

HOLE SIZE: 6 3/4"  
CASING: 4 1/2" @ 3490'  
CEMENTED WITH: 125 SX  
CEMENT TOP: 1679

PERFS:

3401' - 07'  
3411' - 17'

PBTD: \_\_\_\_\_

TD: 3500'