

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 87240

District II

811 South First, Artesia, NM 87210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-21216
1. Type of Well: Oil Well ☐ Gas Well ☐ Other Water Injection		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator Xeric Oil & Gas Corporation		6. State Oil & Gas Lease No. E-4199
3. Address of Operator P. O. Box 352 Midland, TX 79702		7. Lease Name or Unit Agreement Name: Mesa Queen
4. Well Location Unit Letter <u>E</u> : 1650 feet from the <u>North</u> line and 660 feet from the <u>West</u> line Section <u>20</u> Township <u>16S</u> Range <u>32E</u> NMPM Lea County		8. Well No. 24
		9. Pool name or Wildcat Mesa Queen Associated
		10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4353 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- 1) MIRU Pulling Unit.
- 2) Spot 25 sx plug @ 3300' & tag.
- 3) Spot 25 sx plug @ 1300' & tag.
- 4) Cut casing @ 600' & lay down.
- 5) Spot 25 sx, 50' in and out of stub & tag.
- 6) Spot 25 sx @ 50' & bring to surface.
- 7) RD & install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angie Crawford TITLE Production Analyst DATE 5/27/03
Angie Crawford 915-683-3171

Type or print name Telephone No.

(This space for State use)

APPROVED BY Gary W. Wink TITLE OC FIELD REPRESENTATIVE / STAFF MANAGER DATE MAY 30 2003
Conditions of approval, if any:

XERIC OIL & GAS CORP.
WELLBORE DIAGRAM

WELL: Mesa Queen Unit #24

COUNTY: Lea

STATE: NM

HOLE SIZE: 12 1/4"

CASING: 8 5/8" @ 326'

CEMENTED WITH: 200 SX

CEMENT TOP: Surf.

TUBING: _____

RODS: _____

PUMP: _____

PACKER: _____

HOLE SIZE: 7 7/8"

CASING: 4 1/2" @ 3464'

CEMENTED WITH: 200 SX

CEMENT TOP: 1708'

PERFS: _____

3403' - 20'

PBTD: 3420'

TD: 3464'