

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 5-27-2004

FILE IN TRIPLICATE

OIL CONSERVATION DIVISION

DISTRICT I
1625 N. French Dr. , Hobbs, NM 88240

1220 South St. Francis Dr.
Santa Fe, NM 87505

DISTRICT II
1301 W. Grand Ave, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

WELL API NO.	30-025-30204
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	NORTH HOBBS (G/SA) UNIT Section 31
8. Well No.	322
9. OGRID No.	157984
10. Pool name or Wildcat	HOBBS (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	
1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☐ Injector	
2. Name of Operator Occidental Permian Ltd.	
3. Address of Operator 1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200	
4. Well Location Unit Letter <u>G</u> : <u>2480</u> Feet From The <u>NORTH</u> <u>1509</u> Feet From The <u>EAST</u> Line Section <u>31</u> Township <u>18-S</u> Range <u>38-E</u> NMPM <u>LEA</u> County	
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3638' GR	
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit Type _____ Depth of Ground Water _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG & ABANDONMENT ☐
PULL OR ALTER CASING ☐	Multiple Completion ☐	CASING TEST AND CEMENT JOB ☐	
OTHER: _____	☐	OTHER: _____	☐

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RUPU. Pull Injection equipment. Set 5.5" CIBP @4135'.
2. Perforate the following intervals: 4084-89, 4096-4104, and 4110-14 using 2 spf and 180 deg sp ph. (40 holes).
3. Stimulate perms 4089-4114 w/1260 g 15% NEFE HCL acid.
4. RIH w/5.5" UNI VI pc pkr, XL on/off tool w/1.875 ss "F" nipple. 130 jts 2-7/8" Duoline tbg. Pkr set @4021'.
5. Load csg w/100 bbl pkr fluid. Tst csg to 650 psi for 30 min and chart for the NMOCD.
6. RDPU. Clean Location.

Rig Up Date: 08/16/2005
Rig Down Date: 08/19/2005

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Robert Gilbert TITLE Workover Completion Specialist DATE 08/24/2005
TYPE OR PRINT NAME Robert Gilbert E-mail address: robert_gilbert@oxy.com TELEPHONE NO. 505/397-8206

For State Use Only

APPROVED BY Harry W. Wink OC FIELD REPRESENTATIVE II/STAFF MANAGER
CONDITIONS OF APPROVAL IF ANY: _____ TITLE _____ DATE _____

SEP 13 2005

